

***Custom Paper Rotates from Quark 5.0
X12 1.5***

Problems Addressed:

Custom paper size fails to print from bypass tray from Quark 5.0 on Mac OS 9.2 client. (Xerox SPAR # 875110050, EFI Bug # 1-9IAYO)

Solution:

Download the enclosed 1-9IAYO.ps to the Fiery X12 and replace ppd on Mac client.

This update consists of the following file:

File Name	File Size
1-9IAYO.ps	714 KB
Fiery X12 Color Server PS.hqx	151 KB

Important Note:

This patch was tested and approved on a system with X12 1.5 Composite Patch (1-77IXH & 1-6HW61). These patches should be loaded prior to installing this new patch (1-9IAYO).

Installation Instructions:

1. Download 1-9IAYO.ps file via the Fiery Downloader, Web Downloader to the Print Queue or use the import function of CWS 4.x to import to the Hold queue, then print it.
2. In Command Workstation/Spooler (web), verify that 1-9IAYO.ps is in the printed queue.
3. Wait 60 seconds.
4. Select Reboot from the Fiery Control Panel.
5. After the server has restarted, please wait until it goes to idle and print a Configuration Page to verify that the file has been received. The Update Information should contain the patch number 1-9IAYO.

Installation Instructions for Mac client:

Note: The ppd supplied is in bin-hex encoded file to prevent corruption. Before using, it must be decoded using common Mac utilities.

1. Find the file "Fiery X12 Color Server PS" in the System/ Extensions/ Printer Descriptions folder.
2. Replace it with the version supplied with patch.