

D95A/D110/D125 Software Release Notes

Post Launch Maintenance Release

October 2018

Objective of Software Set Release

The all-in-one release announces the availability of the mandatory Maintenance Release Software version 25.14.31 for the D95A, D110, and D125, to address outdated CCC and SHA1 security requirements.

Version and Name of Software Set

Copier/Printer: 25.14.31: D125CP_XC_251431_171006.bin

Note : *This version is based off the previous maintenance release, R5.5. This version is for the Copier/Printer models only. DO NOT install this version on Printer Only models.*

Note : *DO NOT install this software release if your Copier/Printer is already at version 25.14.31 or higher.*

Software Installation Instructions

To determine the currently installed software version:

1. In CentreWare Internet Services, click **Properties > General Setup > Configuration**.
2. Scroll down to **Software** to verify the software version.

To update the software:

1. In CentreWare Internet Services, click **Properties > Services > Machine Software > Upgrades**.
2. Under **Upgrades** select **Enabled**.
3. Click **Apply**.
4. Refresh your browser and navigate to **Properties > Services > Machine Software > Manual Upgrade**
5. Under **Manual Upgrade**, click **Browse** to locate and select the software upgrade file in .bin format.
6. Click **Open**.
7. Click **Install Software**. The file is sent to the printer. Once the software is installed, the printer restarts.
8. Check the configuration report to verify that the software has updated.

Software Version Information

	Version number in new software set	Version number in the previous release R5.5	Notes
Controller - Copier/Printer	1.204.17	1.204.9	
IOT	V84.19.0	V84.13.0	
IFM	V8.77.0	V8.63.0	
HCS	V2.15.0	V2.8.0	
D-Finisher	V5.50.0	V5.29.0	
Perfect Binder	V210.01.0	V210.01.0	Copier/Printer only
PF3.5HCF	V13.08.0	V13.08.0	
IISS	V9.12.0	V9.10.0	Copier/Printer only
DADF	V13.22.0	V13.16.0	Copier/Printer only

Specification Change & Added Feature by Subsystem (changes from R5.5)

	Specification Change & Added Feature
Controller	<ul style="list-style-type: none"> Allow IOT NVM R/W in KO mode. Change the number of asynchronous message queues for BufCont, 10 -->50. SSLv3 vulnerability response. Support for CWIS on Windows10. Increase the ExtPrintCnt stack size. Add a support for SSL using SHA2 Certificate on the products that do not contain the support for encryption algorithm issue in Year 2010. Add the language set for Romanian. Add advanced ScanToHome service (System Login). Disable use of RC4 for SSL connection. Backport of Fix for OSS vulnerabilities (globe,libdecomp). Support for re-acquisition of CC authentication. Add the preventive measures against CWIS XFS (Cross-Frame Scripting).
IOT	<ul style="list-style-type: none"> Install the Perfect binder sequence.
IFM	None
HCS	<ul style="list-style-type: none"> To install the expand of down purge function.
Finisher	<ul style="list-style-type: none"> Modify the Job sequence of B5L and B4S. Change the flapper gate moving specification. Change the Preptime. Added NVM for trimmer clump number. Change the fold adjustment specification. Change the start timing of SCT exit Motor on 1st sheet of punching.
Perfect Binder	None
PF3.5HCF	None
IISS	<ul style="list-style-type: none"> Modify the specification of black line deletion function.
DADF	<ul style="list-style-type: none"> Detection for width about Letter size. Countermeasure for trouble of stop sequence on scanning. Change current value of low level for Platen motor.

AR's (changes from R5.5)

	AR
Controller	<ul style="list-style-type: none"> Machine crashes when a job with a special font glyph is submitted. Printer corrupts HTTPS requests which are larger than 16K. Update behavior of PCL5 macro command. 2-hole stock when stock programmed as Size: Auto Detect, Type: Plain (64-105gsm), Hole Punched box: Checked. When the customer prints a JPG file from his camera by usb port, the result is a 16-721 or 16-731. Page 2 of the customer's document is printed on the back side of the 2nd sheet when printing the job from multiple trays. Error occurs when OCSP response signing certificate with a 4096 bit RSA key is returned during retrieval of Certificate Status. Scan to Email intermittently fails with fault 016-781. While reloading paper M/C freezes. D110 output pauses between sets when the Bluebear FID device is connected. When the FID device is disconnected the sets print without pausing. PCL5 issue -OCR-B font oversize printed. eCopy 5.2 EIP scans with Color Depth = Auto, the job results in an error on the printer LUI and the scan folder does not get deleted from the eCopy scan destination. Equitrac card reader does not function after disabling SSL v3 on the Equitrac Server. Unable to login using a USB connected reader and the Papercut solution v15.1.33408. FC 116-324, 016-720 errors When Printing from IE 10 or 11. Unable to log on randomly due to the card reader plug-in going to an "deactivated" state. Access problem when using USB card reader. Need to correct messages in Romanian translation. Normal user cannot print jobs using "Send from folder" option. When printing tabs from OHCF system always jams in Software 1.204.120 or 1.204.116. Empty page when customer directly prints pdf file from CRM (Customer Relationship Management) System.
IOT	None
IFM	<ul style="list-style-type: none"> Countermeasure for sensor filtering of Punch mode. Fault occurred 49-113 jam with Sparta punch.
HCS	None
Finisher	<ul style="list-style-type: none"> Change the pitch interval for using trimmer. Frequent 012-159 Jams with Unstapled, Small Set. Printer fault 012-114 when printing sequential SRA4, 90gsm size jobs then without delay 320x300mm, 120gsm job. Countermeasure to occur the 45-313 error. Countermeasure to hard moving of stapler. Fault occurred 127-311 error on printing job included insert paper.
Perfect Binder	None
PF3.5HCF	None
IISS	<ul style="list-style-type: none"> Countermeasure to divide the specific detection area on using center erase function.
DADF	<ul style="list-style-type: none"> Countermeasure for 62-311 on scanning. No notification that there is a next original sheet on one page scanning by DADF.