Release Note

General information	
Issue ID Number	1-KRY4Y
Product Name	Docucolor 3535 1.1 English
Issue Date	January 23, 2006

Files included in this release	
File name	**File size**
1-KRY4Y.ps	38 KB
1-KRY4Y_relnotes.doc	

Issue(s) addressed with this release

Incorrect pages are printed when selecting the page range as odd pages in the job properties via Command Workstation.

Steps to reproduce

Application: CWS 4.1.052

1) In Command Workstation, Import a multi-page PDF job to the Fiery Hold queue.
2) Double-click the job to open the job Properties.
3) Change the page range to "Odd"

Result: The printed job has pages missing. The job prints out Page 1, Page 5, Page 9, Page 13, etc…
It should print out all odd numbered pages.

Prerequisite(s)

None

Installation instructions

1. Download/Import the patch file "1-KRY4Y.ps" with Command Workstation to the "Direct" queue.
2. You must wait at least 60 seconds after the patch file downloaded/imported before rebooting the system. This will ensure the patch file is completely processed.
3. Please select "Shut Down" and then "Reboot System" on the Fiery LCD. If your Fiery does not have an LCD, choose Windows Start / Shut Down / Restart. When the Fiery has come to "Idle", repeat the steps to reboot the system.
4. Please wait until the Fiery has come to idle after the second reboot to print out the configuration page.

Verify the **Update Info** section. It should contain the patch number "1-KRY4Y".

Known Issues

None