

DigiPath Customer Bulletin

Configuration: DigiPath 4.x

Release: DigiPath 4.1.0.6

| | |
|---------------------------|--------------------|
| Bulletin Number: | DigiPath 87 |
| Distribution Date: | 7/04 |
| Expiration: | Next release |

Title: Announcing DigiPath Patch Software Version 4.1.0.6 and FreeFlow Scanner 665.

ANNOUNCEMENT:

DigiPath Patch Software Version 4.1.0.6 A new DigiPath baseline patch software version 4.1.0.6 has been released for mass distribution as the new baseline for DigiPath software. This patch should be installed on all DigiPath 4.1 software systems effective 7/20/04. All software support channels will be based on the assumption that all systems have been upgraded to this version. Problems fixed in this patch release will no longer require a SPAR submission.

All DigiPath patches are cumulative which means that all new patches also contain all of the previous patches within them. A listing of all SPARS fixed for each version of patch software is listed below.

FreeFlow Scanner 665 The FreeFlow™ Scanner 665 is a production scanner that provides a cost-effective digital input station for production publishing systems. New features include: improved automatic punched hole detection & removal, interactive preview capability (allowing multiple IQ corrections without the need for document reload), and an Auto-select scan location feature (provides automatic detection of documents placed in the feeder or on the platen). The scanner provides high-speed, black & white text and line art scans. The Integrated Solutions Announcement (ISA) describing the FreeFlow Scanner 665 can be found (after July 15, 2004) on the Web at the following location:

Internal Site

Log on to the [FIC Web Site](http://www.thefic.xerox.com/dsweb/View/Collection-83535) or select the following URL:
<http://www.thefic.xerox.com/dsweb/View/Collection-83535>

Installation Procedures are attached to this bulletin.

DigiPath Patch 4.1.0.6

This software release has been made available to include the necessary software changes to enable the new FreeFlow Scanner 665 for DigiPath 4.1. This does not include any new SPAR fixes.

DigiPath Patch 4.1.0.5

The following fixes, previously reported with DigiPath 4.1.0.5, are also included in DigiPath SPAR patch 4.1.0.6:

- Document Scan and Makeready: Size or position for a fill operation is not preserved
- Document Scan and Makeready: An undo delete adds two unexpected blank pages
- Images are overlaid
- A problem with DigiPath Rescue not restoring
- When importing the RDO files by the particular step, the count of files continues to increase
- Some images are missing when a multi-page TIFF is imported by Document Scan and Makeready
- Network Agent does not work without DocuSP IPP is not available.
- Not displaying Blank Insert Pages of formDescs on Document Scan and Makeready
- Continued Page Numbers in section not working correctly after a TAG
- Unable to production print using client Batch Tool
- [Undo Delete] doesn't work properly

DigiPath Customer Bulletin

- Colorize Fills are shifted a little on an exported PDF
- Within the standard wizard - page numbering is on when not selected.
- An error (S03-4220) occurs when changing output image mode
- Unable to delete page icons
- Certain .prn files aren't a recognized as a file type
- Fault Code 0047-1463 when inserting multiple pdf files from a CD-ROM on DELL Platform
- Unable to import pdf files into Document Scan and Makeready from CD ROM
- An 11x17 with z fold programming does not arrive correctly at the Xerox 2101 Digital Copier
- Batch Tool: [Job Pause] menu starts pending jobs

EXPIRATION: None