

Fiery Patch Release Notes

General information

| | |
|------------------|--|
| Defect ID number | 1-18FEO8 |
| Product name | Fiery Color Integrated Controller For Xerox Color 550/560 v1.0 |
| Release date | January 24, 2011 |

Files included in this release

| File name | File size |
|-------------|-----------|
| 1-18FEO8.ps | 2.09KB |

Issue(s) addressed with this release

- With Secure Erase enabled, Job Properties is slow when jobs are submitted.

Steps to reproduce the Issue(s)

1. Import a 20 page pdf doc to the hold queue.
2. Open Job Properties.
3. Go to Mixed Media settings and set the following settings:
 - a. Pages 1-10, Tray 1, 11x17
 - b. Pages 11-20, Tray 5, 8.5x11 LEF
4. Change copy count to 3 and select print.

Result: User will see extremely long delay in responsiveness on Command WorkStation when Secure Erase is enabled.

Before installing 1-18FEO8.ps

**CAUTION**

- 1 This patch is exclusive, it must be installed by itself, and the server must be rebooted or restarted once. After that, other patches can be applied to the server.
- 2 If any prerequisites listed below, they must be installed in the order specified before applying the 1-19HPAG.ps patch:
 - **1-18OY91**
 - **1-18TDCY**
 - **1-18WR77**
- 3 If any known issues listed below, read before installing **1-18FEO8.ps** patch:
 - None.



Patch installation instruction

1. Make sure that the Fiery is Idle.
2. Import the patch file 1-18FEO8.ps using Command Workstation to the Direct queue.
3. You must wait until the file finishes processing and CWS or LCD show Idle. This ensures the patch file is completely processed. User should wait **60 seconds** for complete installation of patch.
4. From Command WorkStation, choose Server-> Reboot Server, or from the Fiery LCD, select Shut down -> Reboot System.
5. Wait until the Fiery comes to Idle and print the configuration page.
6. Verify that the **System Update Log** contains the patch number 1-18FEO8.