

Fiery Patch Release Notes

General information

Defect ID number	1-18ZL1Q
Product name	Fiery Color Integrated Controller For Xerox Color 550/560 v1.0
Release date	January 18, 2011

Files included in this release

File name	File size
1-18ZL1Q.ps	1.26 MB

Issue(s) addressed with this release

- Contouring in gradient sweeps.

Steps to reproduce the Issue(s)

1. Print a color image with a single color background going from dark to light.

Result: Color transition from dark to light is not smooth. This is more obvious in certain colors.

Note that with this patch, gradients are not fully smooth, but are improved.

Before installing 1-18ZL1Q.ps



1. This patch is exclusive, it must be installed by itself, and the server must be rebooted or restarted once. After that, other patches can be applied to the server.
2. If any prerequisites listed below, they must be installed in the order specified before applying the **1-18ZL1L.exe** patch:
 - **1-18OY91**
 - **1-18TDCY**
 - **1-18WR77**
3. If any known issues listed below, read before installing **1-18ZL1Q.ps** patch:
 - None.

Patch installation instruction

- Make sure that the Fiery is Idle.



- Import the patch file 1-18ZL1Q.ps using Command Workstation to the Direct queue.
- You must wait until the file finishes processing and CWS or LCD show Idle. This ensures the patch file is completely processed. User should wait **60 seconds** for complete installation of patch.
- From Command WorkStation, choose Server-> Reboot Server, or from the Fiery LCD, select Shut down -> Reboot System.
- Wait until the Fiery comes to Idle and print the configuration page.
- Verify that the **System Update Log** contains the patch number 1-18ZL1Q.