

Fiery Patch Release Notes

General information

| | |
|------------------|--|
| Defect ID number | 1-1AOIEP |
| Product name | Fiery Color Integrated Controller For Xerox Color 550/560 v1.0 |
| Release date | June 10, 2011 |

Files included in this release

| File name | File size |
|-------------|-----------|
| 1-1AOIEP.ps | 101 KB |

Issue(s) addressed with this release

- 1-1AOIEP: Cannot staple when using Xerox Mobile Print Solution SP1 (v 1.5.1).

Steps to reproduce the issue(s)

1. With the Xerox Mobile Print Solution installed on the 550/560, submit a multi-page document via email.
2. In the Mobile Print options for the document, select staple, and print the job.

Result: Document prints without stapling.

Before installing 1-1AOIEP.ps



1. This patch is exclusive, it must be installed by itself, and the server must be rebooted or restarted once. After that, other patches can be applied to the server.
 2. If any prerequisites listed below, they must be installed in the order specified before applying the **1-1AOIEP.ps** patch:
 - **1-16C6H7**
-

Patch installation instructions

1. Make sure that the Fiery is Idle.
2. Import the patch file **1-1AOIEP.ps** using Command Workstation to the Direct queue.



- 3 You must wait until the file finishes processing and CWS or LCD show Idle. This ensures the patch file is completely processed. User should wait **60 seconds** for complete installation of patch.
- 4 From Command WorkStation, choose Server -> Reboot Server, or from the Fiery LCD, select Shut down -> Reboot System.
- 5 Wait until the Fiery comes to Idle and print the configuration page.
- 6 Verify that the **System Update Log** contains the patch number **1-1AOIEP**.