

Xerox Color C60/C70 Printer EXi Integrated Fiery® Color Server



Xerox Corporation
800 Phillips Road
Webster, NY 14580

April 2017

Dear Xerox Color C60/C70 EXi Integrated Fiery Color Server customer:

The Xerox Integrated Fiery Color Server for your Xerox Color C60/C70 Printer can now be upgraded with the SP2 software patch.

NOTE: *Your system must be at version 2.0SP1 prior to installing this software.*

We tested this software patch specifically for the System Problem Action Requests (SPARs) noted below. If your SPAR number is not listed, we are providing you this software either because you reported a problem that resembles one of the listed fixes or because our testing has shown that this software should resolve your problem. If this software does not resolve your problem, please contact the hotline and provide a detailed job scenario and sample job(s) for further investigation, testing, and resolution.

This software patch contains fixes :

SPAR #	Description
1. CQGbl01103477	A intermittent DFE error 127-210
2. CQGbl01052395	Unable to set IP address using the device UI.
3. CQGbl01099592	Job stay in the print queue.