
Xerox WorkCentre 7425/7428/7435



Image Quality Defects and Solutions




If you have this...



Replace this...

Problem: Streaks appearing from Lead Edge to Trail Edge

Solution: Replace the Transfer Belt Cleaner




Problem: Marks, bands or spots appearing at intervals of 3.74 inches (95mm) or 1.49 in (38mm).

Solution: Replace the Drum

Page 1 of 2 701P49650

Image Quality Defects and Solutions (continued)


If you have this...



Replace this...

Problem: Marks or lines appearing at intervals of 3.30 inch (84mm)

Solution: Replace the Fuser



Problem: Dents appearing on the back side of the print at intervals of 3.70 inch (94mm)

Cause: A speck of debris has contaminated the Pressure Belt

Solution: Replace the Fuser

Customer Expectation Document
WorkCentre 7132 Multifunction Printer/Copier
For Copier (1997) A 18 A 1997 A

Problem: Bands or deletions appearing at intervals of 2.16 inch (55mm)

Solution: Replace Second Bias

Transfer Roll

Page 2 of 2 701P49650