

Fiery Patch Release Notes

General information

Defect ID number	1-19M53H
Product name	Fiery Network Controller for WorkCentre 7500 Series v1.0
Release date	1/11/2011

Files included in this release

File name	File size
1-19M53H.ps	3,185 KB

Issue(s) addressed with this release

Patch improves gradation smoothness.

Steps to reproduce the Issue(s)

1. Print a color image with a single color background going from dark to light.

Result: Color transition from dark to light is not smooth. This is more obvious in certain colors.

Before installing "1-19M53H.ps"

- 1. This patch is exclusive, it must be installed by itself, and the server must be rebooted or restarted once. After that, other patches can be applied to the server.
- 2. Prerequisite listed below must be installed before applying "1-19M53H.ps" patch:
 - 1-18GCJ1

Note: Print Configuration Sheet to check if patch has been installed.

Note: If patch is not installed it can be found at http://www.support.xerox.com/ or Fiery System Updates.

- 3. Known issues listed below. Read before installing **1-19M53H.ps** patch:
 - None.
- 4. Do <u>NOT</u> install any of the following patch(es) <u>after</u> installing the **1-19M53H.ps** patch. If you are required to install any of the patch(es) below, do so <u>before</u> installing the **1-19M53H.ps** patch:
 - None.





Patch installation instruction

- 1. Make sure that the Fiery is Idle.
- 2. Import the patch file **1-19M53H.ps** using Command Workstation to the Direct queue. Or use Fiery WebTools by going to the Docs tab to Import to Direct queue.
- 3. You must wait until the file finishes processing. Please refer to CWS or WebTools to ensure the patch file is completely processed.
- 4. From Command WorkStation, choose Server → Reboot Server, or from the WC75xx UI select the Fiery Button → Restart Server → login as operator → Reboot System.
- 5. Wait until the Fiery comes to Idle If startup page is enabled on the Fiery Controller, the startup page will print.
- 6. Print a configuration page to verify that the **Update Info** section contains the patch number **1-19M53H**.