

May 2008

Dear DocuColor 242/252/260 customer:

Your DocuColor CX260 system can now be upgraded with the **Patch_Out_of_place** software kit.

NOTE: *This software may be installed by the customer.*

PREREQUISITE(s): *CX260_v2.0_SP1
ATS Firmware 121018Patch 22-Nov-2007*

We tested this updated software release specifically for the System Problem Action Requests (SPARs) noted below. If your SPAR number is not listed, we are providing you this software either because you reported a problem that resembles one of the listed fixes or because our testing has shown that this software should resolve your problem. If this software does not resolve your problem, please contact the hotline and provide a detailed job scenario and sample job(s) for further investigation, testing, and resolution.

This software kit contains fixes for the following SPARs:

SPAR Release		SPAR #	Description
<hr/>			
SPAR kit version			
Patch_Out_of_place	1.	808785843	Tray 6 out of place after Sleep mode.

NOTE: *Not all child SPARs will be listed in this letter.*