Release Note

General information	
Issue ID Number	1-K32ZJ
Product Name	Fiery X12 Color Server v. 1.5 SP2
Issue Date	October 10, 2005

Files included in this release	
File name	**File size**
1-K32ZJ.ps	7.37 Megabytes
1-K32ZJ _relnotes.doc	44 Kilobytes

Issue(s) addressed with this release

Word document not printing correctly when Grayscale is selected.

Steps to reproduce

1. Open test file from MSWord.
2. The document is already set up to print 2-up, 11x17, Landscape.
3. Go into Print and select duplex, grayscale
4. Notice that the 2nd page is either blank (what the customer was getting) or a black digitized sheet will print.

Installation instructions

Patch Installation:

1. Download/Import the patch file "1-K32ZJ.ps" with Command Workstation to the "Direct" queue.
2. You must wait at least 60 seconds after the patch file downloaded/imported before rebooting the system. This will ensure the patch file is completely processed.
3. The system must be rebooted twice for the patch to be effective.
4. Please select "Shut Down" and then "Reboot System" on the Fiery LCD. When the Fiery has come to "Idle", repeat the steps to reboot the system.
5. Please wait until the Fiery has come to idle after the second reboot to print out the configuration page.

Verify the **Update Info** section. It should contain the patch number "1-K32ZJ".

Prerequisite(s)

None.

Known Issues

None.