EFI Fiery™ for the Xerox® EX-i C60/C70 Color Server

PostScript patch release note

Overview

This checklist will help you prepare for the installation of **FIT101556835.ps.**

General Information	
○ Current Version	2.0_SP1
○ Defect ID	FIT101556835.ps
○ Release Date	10-February-2017
○ Files included	FIT101556835.ps
○ File size	303116520 bytes
○ Checksum	2545881862

Issue(s) addressed with this release

- FIT101556835: Fiery Patch to support Advanced Punch Pro Finisher.

- FIT101647380: A5 LEF/SEF offset and A5 LEF punch feature for BR Finisher.

> **IMPORTANT**

Before installing FIT101556835.ps

1. Known issues listed below, read before installing FIT101556835.ps patch:

- This patch obsoletes the patch: **FIT101536749**

2. The following prerequisite(s) must be installed in the order specified before applying the **FIT101556835.ps** patch:

- SP1

- FIT101500095

3. Do NOT install any of the following patch(es) after installing the **FIT101556835.ps** patch. If you must install any of the patch(es) below, do so before installing the **FIT101556835.ps** patch:

- None.

4. This patch is exclusive, it must be installed by itself, and the server must be rebooted or restarted once. After that, other patches can be applied to the server.

Patch installation instructions

1. Make sure that the Fiery controller has reached Idle.

2. Import the patch file **FIT101556835.ps** using Command WorkStation to the Direct connection.

3. You must wait until the file finishes processing and Command WorkStation or the LCD show Idle.

EFI Fiery™ for the Xerox® EX-i C60/C70 Color Server

PostScript patch release note

4. From Command WorkStation, choose Server, Reboot Server, or from the Fiery LCD, select Shut down, Reboot System.

5. Wait until the Fiery controller reaches Idle and print the configuration page.

6. Verify that the Update Info section contains the patch number **FIT101556835**.