Engineering Release Note

General information	
Issue ID Number	1-OQIB9
Product Name	Fiery EXP250 PS v1.01/1.1 EFIGSBPD
Issue Date	August 25, 2006

Files included in this release	
File name	**File size**
1-OQIB9-1.exe	1,125,396 bytes
1-OQIB9_relnotes.doc	46,592 bytes

Issue(s) addressed with this release

When attempting a scan-to-file, the job errors on the machine with a fault code of 016-782, 27-741, or 016-781.

Steps to reproduce

Perform a Scan-to-File job.
Result: Sometimes the printer enters an error condition. Some of the failures include 27-741, 016-781 and 016-782.

Prerequisite(s)

None

Installation instructions

1. Execute 1-OQIB9-1.exe and follow the instructions in the Fiery Patch Downloader
2. Notes about the Fiery Patch Downloader
    a. Login must be “admin”. This is fixed and cannot be modified.
    b. Password is the Fiery administrator login password
    c. Hostname can be either the IP address or the Fiery server name.
3. After the patch is downloaded, and when prompted by Fiery Patch Downloader, choose “Restart Fiery Service”.
4. When the Fiery has come to “Idle”, verify the Update Info section in the Configuration page.
5. It should contain the patch number “1-OQIB9-1”.

Note: When executing “1-OQIB9-1”.exe, if you choose “Reboot/Restart later” when prompted by the Fiery Patch Downloader, please make sure you manually reboot the server for changes to take effect.

Additional Notes

This patch is not intended to clean any current corrupted mailboxes. It changes the behavior of the polling interval to prevent further corruption.