XEROX

Scan Backs too Light
X12 1.5

Problems Addressed:

Scan backs are too light after Composite Patch is loaded. (EFI Bug # 1-90HWH).

Solution:

Download the enclosed 1-90HWH.ps to the Fiery.

This update consists of the following file:

File Name	File Size
1-90HWH.ps	7.04 KB

Important Note:

This patch requires and was tested with X12 1.5 Composite Patch (1-77IXH & 1-6HW61) pre-installed.

Installation Instructions:

1. Download 1-90HWH.ps file via the Fiery Downloader, Web Downloader to the Print Queue or use the import function of CWS 4.x to import to the Hold queue, then print it.
2. In Command Workstation/Spooler (web), verify that 1-90HWH.ps is in the printed queue.
3. Wait 60 seconds.
4. Select Reboot from the Fiery Control Panel.
5. After the server has restarted, please wait until it goes to idle and print a Configuration Page to verify that the file has been received. The Update Information should contain the patch number 1-90HWH.ps.