Release Notes

General information	
Issue ID Number	1-CKV45
Product Name	Xerox EX3535 v1.0
Issue Date	January 15, 2004

Files included in this release	
File name	**File size**
1-CKV45.ps	49.7 KB
Relnotes 1-CKV45.pdf	6.82 KB

Issue description	
Customer requests a patch to disable HTTP Trace	
Steps to reproduce	
N/A	
Resolution type:	**Closed-Patch**
Resolution	
Sending 1-CKV45.ps to the Fiery will disable the HTTP Trace function	
Important notes	

Installation Steps:

1. Download/Import the patch file "1-CKV45.ps" with either “Fiery Downloader” or “Command Workstation” to the "Direct" queue.
2. You must wait at least 60 seconds after the patch file downloaded/imported before rebooting the system. This will ensure the patch file is completely processed.
3. Please select "Shut Down" and then "Reboot System" on the Fiery LCD. If you are using CWS 4, please select “Server” on the menu bar and select “Reboot Server”.
4. After the patch has finished installing, the Print Controller will come to “Idle”.
5. Next, power cycle the copier. The Fiery LCD will prompt you to power cycle the IOT.
6. Please wait until the IOT has come to “Idle” before printing out the configuration page.

Verify the **Update Info** section. It should contain the patch number "**1-CKV45**”.

Created on 1/15/2004
Last Modified on 1/15/2004