# RELEASE NOTES

| General information | |
|---|---|
| **Issue ID Number** | 1-DSRD9 |
| **Product Name** | Fiery on XPe Operating System, languages EFIGSBPD |
| **Issue Date** | 29 April 2004 |

| Files included in this release | |
|---|---|
| **File name** | **File size** |
| 1-DSRD9.ps | 27.3 MB |
| Relnotes.doc | |
| | |
| | |

| Issue description | |
|---|---|
| Problems Addressed:<br>1. XPe cumulative security patch for Fiery running on XPe in languages EFIGSBPD.<br>2. Patch 1-DSRD9 replaces patch 1-D4VEP, as it includes all the fixes from patch 1-D4VEP. | |
| **Steps to reproduce** | |
| n/a | |
| **Resolution type:** | **Closed - Patch** |
| | |
| **Resolution** | |
| 1-DSRD9.ps | |
| **Important notes** | |

Release Note Template Version 1.0
Created on 3/27/2003 2:41 PM
Last Modified on 5/4/2004 8:41 AM

Installation Instructions:
1. Download 1-DSRD9.ps file via the Fiery Downloader or Command Workstation to the “Direct” Queue.
2) After the system returns to 'Idle", wait 60 seconds.
3) Reboot the Print Controller. If your Fiery has an LCD, choose Shut Down, and choose “Reboot System”. If your Fiery Does not have an LCD, use the Windows Start/Shut Down/Restart menu. Turn off your copier.
4) Let Print Controller come to idle.
5) Print the configuration page and make sure the correct information appears (Update Info section should contain the patch number 1-DSRD9.

Important Note: This patch installs the following MS hotfixes on the Fiery:

| QFE# | MS Patch | Description |
|---|---|---|
| 824146 | MS03-039 | Remote Procedure Call Service Update |
| 330994 | MS03-014 | Cumulative Patch for Outlook Express |
| 823559 | MS03-023 | Buffer Overrun in HTML Converter Could Allow Code execution |
| 815021 | MS03-007 | Unchecked Buffer In Windows Component Could Cause Server Compromise |
| 828750 | MS03-040 | Cumulative Update for Internet Explorer |
| 823182 | MS03-041 | Vulnerability in Authenticode Verification could allow Remote Code Execution |
| 828035 | MS03-043 | Buffer Overrun in Messenger Service Could Allow Code Execution |
| 819696 | MS03-030 | Unchecked Buffer in DirectX Could Enable System Compromise |
| 825119 | MS03-044 | Buffer Overrun in Windows Help Support Cntr Could Lead to System Compromise |
| 824105 | MS03-034 | Flaw in NetBIOS Could Lead to Information Disclosure |
| 832894 | MS04-004 | Cumulative Security Update for Internet Explorer |
| 828028 | MS04-007 | MS Bulletin MS04-007 ASN.1 Vulnerability Could Allow Code Execution |
| 835732 | MS04-011 | April 2004: Security Update for Windows XP Embedded with SP1 (835732) |
| 832483 | MS04-003 | Buffer Overrun in MDAC Function Could Allow Code Execution |
| 824141 | MS03-045 | Buffer Overrun in the ListBox and in the ComboBox Control Could Allow Code Execution |
| 821557 | MS03-027 | Unchecked Buffer in Windows Shell Could Enable System Compromise |