Release Note

General information	
Issue ID Number	1-LOMP3
Product Name	DC3535 v1.1 English
Issue Date	June 2, 2006

Files included in this release	
File name	**File size**
1-LOMP3.ps	50 KB
1-LOMP3_relnotes.doc	

Issue(s) addressed with this release

Ripped jobs archived on the Fiery loses raster data when re-imported

Steps to reproduce

1) Load CWS and send a job to the hold queue
2) Do a Rip and Hold on that job
3) Right click on the job and Archive it. Choose Server Internal
4) In the Archive Tab, select the job you just archived.
5) Right click the job and click Hold.

Result: The job will be moved to the hold queue but the raster information is lost

Prerequisite(s)

1-GUITT

Installation instructions

1. Download/Import the patch file "1-LOMP3.ps" with *Command Workstation* or the *WebDownloader* to the "Direct" queue.
2. You must wait at least 60 seconds after the patch file has downloaded/imported before rebooting the system. This will ensure the patch file is completely processed. A page will be printed confirming that the patch has been downloaded successfully.
3. The system must now be power-cycled for the patch to take effect. Power the system down using the power switch on the front of the copier, wait for it to shut off completely, and then turn it back on.
4. Please wait until the Fiery has come to idle after the reboot to print out the configuration page.

Verify the Updated Information section of the configuration page. It should contain the patch number “1-LOMP3”.

Known Issues

None