# Release Note

| General information | |
|---|---|
| **Issue ID Number** | 1-LTOIW |
| **Product Name** | Fiery Network Controller for DC3535 v. 1.1 |
| **Issue Date** | March 17, 2006 |

| Files included in this release | |
|---|---|
| **File name** | **File size** |
| 1-LTOIW.ps | 1.78 Megabytes |
| 1-LTOIW_relnotes.doc | 48 Kilobytes |

## Issue(s) addressed with this release

DC3535 crashes when submitting PDF through CWS.

## Steps to reproduce

The pdf file contains an embedded ICC profile attached to a grayscale image. When this file is submitted to Print on the DC3535, the system hangs and requires a software reload to recover.

## Prerequisite(s)

1-GUITT

## Installation instructions

1. Download/Import the patch file “1-LTOIW.ps” with Command Workstation to the “Direct” queue.
2. Allow the file to finish processing. A patch page will be printed confirming that the patch has been downloaded successfully.
3. The system must be power-cycled for the patch to take effect. Power down the system using the power switch on the front of the copier, wait for it to shut off completely, then turn it back on.
4. Please wait until the Fiery has come to idle after power-cycling to print out the configuration page.

Verify the **Update Info** section. It should contain the patch number “1-LTOIW”.

## Known Issues

N.A.