XEROX

Windows 2000 Drivers
Fiery Si v1.2

Problem:

Unable to print to the Fiery Si Print Server on the Windows 2000 operating system with currently supplied drivers.

Solution:

Install the printer using the included driver files listed below.

These drivers are considered final release. This means that these drivers have been released <u>as is</u>. Validation was performed and all issues found are listed below. Further testing will not be conducted nor supported.

This update consists of the following (5) files for each language:

File Name	File Size
Efsix203.ppd	31.9 KB
Efsix303.ppd	31.9 KB
Efsix503.ppd	63.1 KB
Efsix703.ppd	35.1 KB
Oemsetup.inf	3.7 KB

Installation Instructions:

1. Go to **Start/Settings/Printers** and double-click on **Add Printer**
2. Follow the On-screen instructions

Note: When installing the printer driver, you will be asked for additional files. These files will be found on the Windows 2000 CD.

Known Issues:

1. 5760\65 only –Printing through TCP/IP is not supported.   When setting the lpr queue to print_5760\65, hold_5760\65, or direct_5760\65, Windows 2000 does not accept characters (\. /, +, =, Etc). You must use Novell when printing with the Fiery Si to a 5760\65 copier.
2. Job Notes are not supported.
3. Custom Paper sizes are not supported

Fiery Utilities are not supported on the Windows 2000 operating system.