

# Release Note

General information	
Issue ID Number	1-GF4I9
Product Name	Fiery EX2101 v2.1
Issue Date	November 5, 2004

Files included in this release	
File name	File size
1-GF4I9.sit.hqx	13.8 Megabytes
Relnotes.pdf	

Issue description	
At Mac OS X CWS LE, cannot always change qty to 4 digits (9999)	
Steps to reproduce	
<ol style="list-style-type: none"><li>1. Connect to a 2101 with 1-DU8WY (v2.1) installed.</li><li>2. At a Mac OS X, use WebTools Installer to download the CWS LE.</li><li>3. Install the CWS LE and connect to the 2101 running v2.1 software.</li><li>4. Select any job at the CWS, either double click or right click and select [Properties].</li><li>5. Select [Job] and change the 'Copies' to something greater than 999, such as 1500.</li></ol> <p>RESULTS: A fault may be raised stating that a number between 1.0 and 999.0 must be entered. If 9999 is entered, the job at the CWS defaults to 999.</p>	
Resolution type:	Closed - Patch
Resolution	
1-GF4I9.zip	

Important notes
<b>Installation Steps:</b> <ol style="list-style-type: none"><li>1. If previous version of CWS LE is installed, please delete CWS LE folder from MacOSX system under: \\Application\Fiery\</li><li>2. Double click on the “1-GF4I9.sit.hqx” and extract “1.0.089” folder on MacOSX desktop.</li><li>3. Open the folder and double click on “Command Workstation LE”, application installer will start to install CWS LE to the system.</li><li>4. Please follow the pop up windows instruction to finish installation.</li><li>5. By default, CWS LE should be located at: Applications\Fiery\CWS LE\CWS LE</li></ol> <p>Verify the <b>Utility version</b> information. It should be “<b>CWS LE 1.0.089</b>”.</p>

Known Issues
No known issues