

October 2011

Dear Xerox XC550/560 Integrated Fiery Color Server customer:

Your XC 550/560 Integrated Fiery Color Server can now be upgraded with the **1-1B2P62** software patch.

**NOTE:** *Your system must be at version 1.0 prior to installing this software.*

We tested this software patch specifically for the System Problem Action Requests (SPARs) noted below. If your SPAR number is not listed, we are providing you this software either because you reported a problem that resembles one of the listed fixes or because our testing has shown that this software should resolve your problem. If this software does not resolve your problem, please contact the hotline and provide a detailed job scenario and sample job(s) for further investigation, testing, and resolution.

This software patch contains fixes for the following SPARs:

SPAR #	Description
1. 519237044	<b>Face-Down printing option is missing under configure from CWS</b>
2. 155183044	<b>Poor quality platen scan results.</b>
3. 336502661	<b>Not able to offset half-z-fold sheets in ps driver</b>
4. 003881522	<b>Specifying print range to print page 1 does not work</b>

**NOTE:** *Not all child SPARs will be listed in this letter.*

Prerequisites:

- 1-16C6H7
- SP1.1
- 1-1BCJPT
- 1-1CBICY