

# Patch Installation Instructions

XOG DFE SPAR Team

|  |                            |
|--|----------------------------|
| Product(s):<br><b>DocuColor 242/252/260 Integrated Fiery Color Server v2.0</b> | Date:<br><b>03/18/2013</b> |
| Title:<br><b>1-1J9XUG Installation Instructions</b>                            | Page:<br><b>1 of 1</b>     |

## Purpose

This software patch provides a 2.0 software update in response to a DocuColor 242/252/260 Integrated Fiery Color Server SPAR. Refer to the included customer letter for more information.

In the event of a 2.0 system reinstall this software should be reapplied.

- \_\_\_ 2. You must wait at least 60 seconds after importing the patch file before rebooting the system. This will ensure the patch file is completely processed.
- \_\_\_ 3. From Command Workstation, select **Server > Reboot Server**. The Fiery will reboot.
- \_\_\_ 4. Wait until the Fiery has come to idle and print out the configuration page.
- \_\_\_ 5. Verify the **Update Info** section. It should contain the patch number **1-1J9XUG**.

## Kit Contents

| Qty. | Description                     |
|------|---------------------------------|
| 1    | Patch Installation Instructions |
| 1    | Customer Letter                 |
| 1    | 1-1J9XUG.ps                     |

## Prerequisites

- Previous working knowledge with the DocuColor 242/252/260 Integrated Fiery Color Server.
- The DocuColor 242/252/260 Integrated Fiery Color Server must be at version 2.0 prior to performing this install. This software is supplemental to the 2.0 launch software.
- PRODIG
- 1-U8E58
- 1-18SMZM
- 1-1E21N4
- 1-13LK3J
- 1-19AZVM
- 1-1CNL1W
- 1-1H1YIQ
- 1-1FLFQA
- 1-1IJ6ZK

## Installation Instructions

**NOTE:** The customer or a member of the Xerox Service Team may install this software.

### 1-1J9XUG:

Before upgrading the software, ensure there are no other jobs processing.

- \_\_\_ 1. Import the patch file **1-1J9XUG.ps** with Command Workstation to the **Direct** queue.