

Release Note

General information	
Issue ID Number	1-IT2OF
Product Name	Fiery X12 1.5 SP2
Issue Date	28 October 2005

Files included in this release	
File name	File size
1-IT2OF.ps	304 Kilobytes
1-IT2OF_relnotes.doc	

Issue(s) addressed with this release

SPAR 258688761 / When printing 2 copies of PS Test Page, X12 displays "Ready within 1 minute" in between jobs, and engine cycles down.

Steps to reproduce

1. Connect CWS to Fiery X12 1.5 SP2.
2. Go to Print Pages, select PS Test Page, select 2 copies and print.
3. You will notice that between the two prints the DC12 will cycle down and a message will come up "Ready within 1 minute."

Installation instructions

1. Download/Import the patch file "1-IT2OF.ps" with Command Workstation to the "Direct" queue.
2. You must wait at least 60 seconds after the patch file downloaded/imported before rebooting the system. This will ensure the patch file is completely processed.
3. The system must be rebooted twice for the patch to be effective.
4. Please select "Shut Down" and then "Reboot System" on the Fiery LCD. When the Fiery has come to "Idle", repeat the steps to reboot the system.
5. Please wait until the Fiery has come to idle after the second reboot to print out the configuration page.

Verify the **Update Info** section. It should contain the patch number "1-IT2OF".

Prerequisite(s)

None.

Known Issues

None.