

Microsoft Security Bulletin MS03-043
EX12 v2.0, XP12 1.1 SP1, X12 v1.5, & X40 1.0

Problems Addressed:

Addresses the Microsoft Security Bulletin MS03-043 and Microsoft Hot fix Q828035. (EFI Bug #1-BZMY6)

For more details about MS03-043, please see Microsoft's Website:

<http://support.microsoft.com/default.aspx?scid=kb;en-us;828035>

<http://www.microsoft.com/technet/treeview/default.asp?url=/technet/security/bulletin/MS03-043.asp>

Solution:

Download the enclosed 1-BY9BS.ps to the Fiery Server.

This update consists of the following file:

File Name	File Size
1-BY9BS.ps	3.9 MB

Important Note:

Microsoft NT Service Pack 6a is required prior to installation of the hot fix patch 1-BY9BS.

EX12 v2.0 – SP6a is installed on system at launch and software installation.

XP12 v1.1 SP1 – SP6a is installed on system at upgrade with patch 1-6WXPM.

X12 v1.5 – SP6a patch 1-77IXH is installed as part of the X12 1.5 Cumulative Pack Kit, Part # 301K12670.

X40 1.0 – SP6a patch 1-ANKZ9 is installed as part of the X40 1.0 Microsoft Security Patch Kit, Part # 301K13180.

Installation Instructions:

1. Download 1-BY9BS.ps file via the Command Workstation 3.x Downloader, Fiery Downloader or Web Downloader to the Direct queue.

Note: Downloading via Command WorkStation, refer to the Job Management Guide

Downloading via Fiery Downloader, refer to the Printing Guide

Downloading via Web Downloader, refer to the Printing Guide

2. Wait 60 seconds.
3. Reboot the Fiery server from the Fiery Control Panel.
4. Fiery server will boot up and then reboot itself.
5. After the server has restarted, please wait until it goes to idle and print a Configuration Page to verify that the file has been received. The Update Information should contain the patch number 1-BY9BS.