

Indecipherable Code
X12 1.5

Problems Addressed:

Output from Quark XPress will print several pages of indecipherable code. (Xerox SPAR # 607782288, EFI Bug # 1-5R3CP)

Solution:

Download the enclosed 1-5R3CP.ps file to the Fiery.

This update consists of the following file:

File Name	File Size
1-5R3CP.ps	7.25 MB

Installation Instructions:

1. Download 1-5R3CP.ps file via the Fiery Downloader, Web Downloader or use the import function of CWS 4.x to import to the Print queue.
2. In Command Workstation/Spooler (web), verify that 1-5R3CP.ps is in the printed queue.
3. Wait 60 seconds.
- 4a. On a Fiery with FACI interface kit, choose Start; Shut down, Restart, and go to step 5.
- 4b. On a Fiery without FACI interface kit, press the menu button under the LCD display, select Shut Down, and select Reboot System.
5. After the server has restarted, please wait until it goes to idle and print a Configuration Page to verify that the file has been received. The Update Information should contain the patch number 1-5R3CP.ps.

Note:

Be sure to have this patch loaded after 1-6HW61 (Composite Patch). If 1-6HW61 is loaded after this patch, please load 1-5R3CP again.

You do not need 1-6HW61 loaded in order for this patch to work.