

Copier Cycling or Jams *X12 1.5*

Problems Addressed:

When printing large 11x17 /A3 duplex documents the copier goes into a cycle mode or a paper jam occurs. (Xerox SPAR #276201593, EFI Bug # 1-6DA71. Xerox SPAR # 183157205, EFI bug # 1-7B20L)

Solution:

Download the enclosed 1-7ZLKZ.ps to the Fiery.

This update consists of the following file:

File Name	File Size
1-7ZLKZ.ps	7.25 MB

Installation Instructions:

1. Download 1-7ZLKZ.ps file via the Fiery Downloader, Web Downloader to the Print Queue or use the import function of CWS 4.x to import to the Hold queue, then print it.
2. In Command Workstation/Spooler (web), verify that 1-7ZLKZ.ps is in the printed queue.
3. Wait 60 seconds.
4. Select Reboot from the Fiery Control Panel.
5. After the server has restarted, please wait until it goes to idle and print a Configuration Page to verify that the file has been received. The Update Information should contain the patch number 1-7ZLKZ.ps.

Important Note:

This patch was tested and approved on a system with X12 1.5 Composite Patch (1-77IXH & 1-6HW61). These patches should be loaded prior to installing this new patch (1-7ZLKZ).

If 1-77IXH & 1-6HW61 is loaded on the Fiery X12 server, please be sure that this patch (1-7ZLKZ) is loaded afterwards.