



Fiery Software Release Notes

General information

Defect ID number	1-1EANRB
Product name	Fiery Network Controller for Xerox WorkCentre 7400 Series
Release date	5 May 2012

Files included in this release

File name	File size	Checksum
XC_WorkCentre74xx_v1_0_OSX_Rel3.0.dmg	44.0 MB	3b1343c54e69641dace65c41862ce795

Issue addressed with this release

- Updated native drivers for full Mac OS X 10.7 compatibility.



CAUTION

Before installing the drivers

1. Please refer to Addendum for additional information regarding this release.

Mac driver installation instructions

OS10.7 – Driver Plug-in Version: 3.2.027.1

1. Decompress XC_WorkCentre74xx_v1_0_OSX_Rel3.0.dmg file on the desktop.
2. Select User Software folder and double click on the Fiery Driver installer.
3. Follow the instructions in the wizard and complete the installation.
4. Navigate through System Preference and install the printer.

Addendum- Notes Fiery Mac OS X v10.7 printer driver

The Mac OS X v10.7 driver installer package is distributed as a disk image (DMG) file, and is named XC_WorkCentre74xx_v1_0_OSX_Rel3.0.dmg. Once the DMG file is downloaded and the disk image is mounted on the computer, the User Software package contains the following:

Fiery Driver Installer – directly installs the printer driver.

Fiery Software Uninstaller - uninstalls printer driver software. This was previously available with the Utilities and is now available as a part of the driver package.


OS versions supported: These printer drivers are supported on Mac OS X v10.5, v10.6 and v10.7.

Mac OS X v10.7 printer driver modifications


Apple® has made significant changes to the way certain applications interact with printer drivers on the new Mac OS X v10.7 operating system (also known as Lion), which affects printing from such applications.

In accordance with the changes Apple imposed on the printer driver software with the new Mac OS X v10.7 operating system, the following modifications have been made in the Mac OS X v10.7 Fiery printer driver:

- The “Click here to access Fiery Utilities” link in the About tab, which launches Fiery Web Tools, has been removed.
- The “Import All” and “Export All” presets features from Preset > Manage Local Presets has been removed.




OS X 10.6




OS X 10.7

- The “Bonjour > Configure” button in the Quick Access tab has been removed. The IP address of the server will automatically appear if it can be resolved correctly or the user has the option of manually entering a server IP address for Two-Way Communication.




OS X 10.6




OS X 10.7

- The “Preview Master” function in the VDP tab has been removed.



OS X 10.6



OS X 10.7



- The “Preview Master” feature in Enable Enhanced FreeForm -> Define Mapping has been removed (product specific).

Known Limitations:

- IPP printing on Mac OS 10.7: While adding a printer on Mac OS 10.7, if the ‘Internet Printing Protocol’ is selected and the queue is set to ‘Hold’, the jobs will not reach the Fiery. This is due to both a 10.7 limitation and to new changes required on the Fiery server.
- While the driver establishes communication with the server, the queries are listed as a job in the ‘print queue’ UI on the client Mac. These queries are not real jobs and will disappear from the ‘print queue’ UI once the query is completed. Apple has acknowledged this to be a bug.
- If an older Mac OS version 10.6.x is upgraded to Mac OS version 10.7.x on the same client Mac, it is required to remove the previous installation of the driver using the Fiery Software Uninstaller (shipped with the DMG) and reinstall the driver. This new driver will print with all EFI-supported applications on Mac OS 10.7.
- Printing via SMB using a Windows shared printer is not supported on Mac OS 10.7.
- Problem with Finishing or Installable options when multiple EFI 10.7 drivers are installed on same client. The finishing or installable options are handled by Mac and not by our Fiery driver. To resolve this issue the workaround is to “configure newly installed OS 10.7 driver to default if there are multiple Fiery drivers on the client machine”.