



Fiery Patch Release Notes

General information

Defect ID number	1-1IAB3B
Product name	Fiery Network Controller for WorkCentre 7500 Series
Release date	18 June 2013

Files included in this release

File name	File size	Checksum
1-1IAB3B.ps	15.7 MB	4169663828

Issue(s) addressed with this release

- **1-1IAB3B Composite patch for Fiery Network Controller for Work Centre 7500 Series.**
- **1-18GCJ1 Composite patch for Fiery Network Controller for Work Centre 7500 Series.**
- 1-17MOEY: CWS/Device Center/General Info: No localized strings display under Consumables > Other.
- 1-17XU18: Top Punch 2/4 holes and Top Dual and Quad Staples does not work when Cover Page is ON.
- 1-180DSU: Web LCD and CWS display question marks and squares when printing from USB.
- 1-184RKH: The output images printed after a blank insert are rotated 180 degrees.
- 1-18660L: Default paper size for all languages keeps changing from A4 to Letter and Letter to A4.
- 1-1866MT: Error message should not display in CWS when Tray 6 is open.
- 1-186IWR: The output is not stapled when inserting a blank page before Page 1 with staple settings is selected.
- 1-187HJP: Server hangs during booting up after enabling set time and date automatically.
- 1-188MAD: When connected to a network that does not have a DHCP server, a local address link is not assigned.
- 1-18DM5D: Bonjour Certification fails.



- 1-18DWC1: Only one copy is printed when PS Cover Page or Slip Sheet is enabled with multiple copies selected.
 - 1-18FG1L: Bi-Di doesn't detect Envelope Tray.

 - **1-1AKUJI Composite patch for Work Centre 7500.**
 - 1-198JNP: Fiery icon is not displayed when connected to the WorkCentre 75xx for the first time or after the WorkCentre 75xx software has been reinstalled.
 - 1-19FU5H: When Secure Erase is enabled, Job Properties in CWS acting slow when submitting job.
 - 1-19KDFE: All jobs printed to Upper Center Tray with errors.
 - 1-19M53H: Patch to improve gradation smoothness.
 - 1-19SQ4A: Receive error when trying to enable logging on the Fiery Controller. Logging is for troubleshooting purposes only.
 - 1-1ADP4T: Composite patch for 1-194XSH and 1-1AAEM5
 - 1-194XSH: Equitrac Office can't retrieve JBA data from device, therefore non-print jobs will not be charged.
 - 1-1AAEM5: Print output is in B&W after enabling then disabling Xerox Standard Accounting – Color tracking only
 - 1-18Z5UE: Patches on GRAD Server get installed automatically even System Update is disabled.

 - **1-1ASO4D Patch to enable Direct Mobile Printing.**

 - **1-1BZ46X Cumulative patch for the following defects 1-1BZ46X, 1-1D6C7E and 1-1DGB2Z.**

 - **1-1BZ6T8 Patch to remove constraints between Perfect Booklet and Bi-Fold.**

 - **1-1CKRSA Configure page displays incorrect Finisher name.**

 - **1-1FS0NN Patch to address Hostname issue when Fiery is in DHCP.**
-

Before installing 1-1IAB3B.ps



- 1 Known issues listed below, read before installing **1-1IAB3B.ps** patch
 - None.
 - 2 Following prerequisite(s) must be installed in the order specified before applying the **1-1IAB3B.ps** patch:
 - None.
 - 3 Do **NOT** install any of the following patch(es) after installing the **1-1IAB3B.ps** patch. If you must install any of the patch(es) below, do so before installing the **1-1IAB3B.ps** patch:
 - None.
 - 1 This patch is exclusive, it must be installed by itself, and the server must be rebooted or restarted once. After that, other patches can be applied to the server.
-

Patch installation instruction

- 1 Make sure that the Fiery is Idle.
- 2 Import the patch file **1-1IAB3B.ps** using Command Workstation to the Direct queue.
- 3 You must wait until the file finishes processing and CWS or LCD show Idle. This ensures the patch file is completely processed.
- 4 From Command WorkStation, choose Server-> Reboot Server, or from the Fiery LCD, select Shut down -> Reboot System.
- 5 Wait until the Fiery comes to Idle and print the configuration page.
- 6 Verify that the **System Update Log** contains the patch number **1-1IAB3B**.