

# EFI Fiery™ for the Xerox® 570 Integrated Color Server

PostScript patch release note



## Overview

This checklist will help you prepare for the installation of **SP3.ps**

General Information	
○ Current Version	1.0
○ Defect ID	FIT100887583
○ Release Date	9-February-2015
○ Files included	Integrated_Fiery_570_v1.0_SP3.ps
○ File size	10055425 bytes
○ Checksum	2114906353

## Issue(s) addressed with this release

- **FIT100887583: Service pack 3 for Xerox EXi 570**
- FIT100868547: when printing page exception page it will not pull the correct paper.
- FIT100868632: Unable to print Tab stock or HW Tab Stock from Internal Trays.
- FIT216282: Large file will not resume after tray empty or toner being added.
- FIT100512336: Tray 5 does not update with new media size information.
- FIT222599: Cover page support for Xerox EXi 570
- FIT222323: COREL X7 jobs are getting rotated and cropped
- FIT100537507: Scanning to a folder using SMB will drop scans

## IMPORTANT

### Before installing SP3.ps

1. Known issues listed below, read before installing **SP3.ps** patch:
  - **This service pack patch obsoletes the below defects: FIT100868632, FIT216282, FIT100512336, FIT222599, FIT222323, and FIT100537507**
2. The following prerequisite(s) must be installed in the order specified before applying the **SP3.ps** patch:
  - SP1
  - SP2
3. Do NOT install any of the following patch(es) after installing the **SP3.ps** patch. If you must install any of the patch(es) below, do so before installing the **SP3.ps** patch:

#### Disclaimer

This hardware, software/patches, or technology may contain cryptographic functions as defined in Article 8 (ix) (h) because the cryptographic capability is not user-accessible, and are designed to have only one or more of the following cryptographic functionality(ies):

1. Functionality to execute copy-protected programs
2. Functionality to access to digital contents stored on copy-protected read-only media
3. Functionality to access to encrypted and memorized digital contents on a medium that will be sold to the public with the same content
4. Functionality for copying control of copyright protected audio/video data
5. Functionality to encrypt and/or decrypt to protect libraries, design attributes, or associated data for the design of semiconductor devices or integrated circuits

# EFI Fiery™ for the Xerox® 570 Integrated Color Server

## PostScript patch release note



- None.
4. This patch is exclusive, it must be installed by itself, and the server must be rebooted or restarted once. After that, other patches can be applied to the server.

---

### Patch installation instructions

1. Make sure that the Fiery controller has reached Idle.
2. Import the patch file **SP3.ps** using Command WorkStation to the Direct connection.
3. You must wait until the file finishes processing and Command WorkStation or the LCD show Idle.
4. From Command WorkStation, choose Server, Reboot Server, or from the Fiery LCD, select Shut down, Reboot System.
5. Wait until the Fiery controller reaches Idle and print the configuration page.
6. Verify that the Update Info section contains the patch number **SP3**.

#### Disclaimer

This hardware, software/patches, or technology may contain cryptographic functions as defined in Article 8 (ix) (h) because the cryptographic capability is not user-accessible, and are designed to have only one or more of the following cryptographic functionality(ies):

1. Functionality to execute copy-protected programs
2. Functionality to access to digital contents stored on copy-protected read-only media
3. Functionality to access to encrypted and memorized digital contents on a medium that will be sold to the public with the same content
4. Functionality for copying control of copyright protected audio/video data
5. Functionality to encrypt and/or decrypt to protect libraries, design attributes, or associated data for the design of semiconductor devices or integrated circuits