



Fiery Patch Release Notes

General information

| | |
|------------------|--|
| Defect ID number | 1-1K3NLJ |
| Product name | Xerox® EX 560 Print Server Powered by Fiery v2.0 |
| Release date | 20 June 2013 |

Files included in this release

| File name | File size | Checksum |
|-----------------|-----------|------------|
| EX560_2_SP1.exe | 3.12 MB | 2848554678 |

Issue(s) addressed with this release

- **1-1K3NLJ: Service Pack 1 for Xerox EX 560 Print Server v2.0.**
- 1-1K3IHX: "Error: DLC error flag set, abort page." is encountered when printing this file.
- 1-1K3DZL: PS error with 1.1SP2. PS undefined result error, offending command "execform".
- 1-1K3DZD: job will not print when machine in energy saver mode
- 1-1K3DZ5: Getting an error when doing booklet to a c2 finisher. on coated 1.

Before installing EX560_2_SP1.exe

IMPORTANT

- 1 Known issues listed below, read before installing **EX560_2_SP1.exe** patch:
 - None.
- 2 The following prerequisite(s) must be installed in the order specified before applying the **EX560_2_SP1.exe** patch:
 - None

Disclaimer

This hardware, software/patches, or technology may contain cryptographic functions as defined in Article 8 (ix) (h) because the cryptographic capability is not user-accessible, and are designed to have only one or more of the following cryptographic functionality(ies):

- 1 Functionality to execute copy-protected programs
- 2 Functionality to access to digital contents stored on copy-protected read-only media
- 3 Functionality to access to encrypted and memorized digital contents on a medium that will be sold to the public with the same content
- 4 Functionality for copying control of copyright protected audio/video data
- 5 Functionality to encrypt and/or decrypt to protect libraries, design attributes, or associated data for the design of semiconductor devices or integrated circuits



- 3 Do **NOT** install any of the following patch(es) after installing the **EX560_2_SP1.exe** patch. If you must install any of the patch(es) below, do so before installing the **EX560_2_SP1.exe** patch:
 - None.
- 4 This patch is exclusive, it must be installed by itself, and the server must be rebooted or restarted once. After that, other patches can be applied to the server.

Patch installation instructions

- 1 Make sure that the Fiery printer controller reaches Idle.
- 2 Execute **EX560_2_SP1.exe** and follow the instructions in the Fiery Patch Downloader.
- 3 Notes about the Fiery Patch Downloader
 - a. Logon must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be the IP address or the Fiery server name.
- 4 After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot. *(If you choose to Restart later, make sure you manually reboot the server for the changes to take effect)*
- 5 Wait until the Fiery controller reaches Idle and print the Configuration page.
- 6 Verify that the **System Updates Log** section contains the patch number **EX560_2_SP1**.

Disclaimer

This hardware, software/patches, or technology may contain cryptographic functions as defined in Article 8 (ix) (h) because the cryptographic capability is not user-accessible, and are designed to have only one or more of the following cryptographic functionality(ies):

- 1 Functionality to execute copy-protected programs
- 2 Functionality to access to digital contents stored on copy-protected read-only media
- 3 Functionality to access to encrypted and memorized digital contents on a medium that will be sold to the public with the same content
- 4 Functionality for copying control of copyright protected audio/video data
- 5 Functionality to encrypt and/or decrypt to protect libraries, design attributes, or associated data for the design of semiconductor devices or integrated circuits