

Release Notes

General information	
Issue ID Number	1-GMHKH
Product Name	EX3535 v1.0 English
Issue Date	December 16, 2004

Files included in this release	
Folder name	File size
1-GMHKH.ps	2.45 MB
Relnotes.pdf	

Issue description	
Customer request to upgrade to latest Apache Web Server version.	
Steps to reproduce	
Network scan indicates that Apache web server current version is 1.3.27. Customer is requesting latest version of Apache Web server 1.3.33 to be installed on the EX3535	
Resolution type:	Closed - Patch
Resolution	
Send 1-GMHKH.ps to the Fiery.	
Important notes	
Installation Steps: <ol style="list-style-type: none">1. Download/Import the patch file "1-GMHKH.ps" with Command Workstation to the "Direct" queue.2. You must wait at least 60 seconds after the patch file downloaded/imported before rebooting the system. This will ensure the patch file is completely processed.3. Please select "Shut Down" and then "Reboot System" on the Fiery LCD.4. Please wait until the Fiery has come to idle to print out the configuration page. Verify the Update Info section. It should contain the patch number "1-GMHKH".	

Known Issues
None