

# RELEASE NOTES

General information	
Issue ID Number	1-FLR0U
Product Name	Fiery EX3535 v. 1.0
Issue Date	October 1, 2004

Files included in this release	
File name	File size
1-FLR0U.ps	744 Kilobytes
relnotes.pdf	

Issue description
Unable to change Server Name using LCD screen/buttons of EX3535.

Steps to reproduce
Use the Fiery LCD screen to enter setup and change the server name of the EX3535. The reconfiguration appears to take, but after reboot the server name remains the same. If other settings in server setup are changed (example: time zone) the changes take place upon reboot. Note: Changing the name via WebTools works as expected.

Resolution type:	Closed - Patch
------------------	----------------

Resolution
1-FLR0U.ps

Important notes
To install this patch, follow these steps:  1. Download the file using Fiery Downloader or Command Workstation to Direct Queue. 2. Allow the file to finish processing and wait at least 1 minute, then power down the server. Power the copier down using the power switch on the front of the copier, wait for it to shut off completely. 3. Power up the server. After the server has reached idle, power up the copier. 4. Print a configuration page to confirm installation. The Update Info should contain the patch number "1-FLR0U"

Release Note Template Version 1.0  
Created on 10/1/2004 2:43 PM  
Last Modified on 10/1/2004 3:00 PM

