

Patch Installation Instructions

XOG DFE SPAR Team

Product(s):	XC 550/560 Integrated Fiery Color Server	Date:	09/13/11
Title:	Integrated_550_560_SP1.1.ps Installation Instructions	Page:	1 of 1

Purpose

This software patch provides a 1.0 software update in response to a XC550/560 Integrated Fiery Color Server SPAR. Refer to the included customer letter for more information.

In the event of a system reinstall this software should be reapplied.

Kit Contents

Qty.	Description
1	Patch Installation Instructions
1	Customer Letter
1	Integrated_550_560_SP1.1.ps

Prerequisites

- Previous working knowledge with the XC 550/560 Integrated Fiery Color Server.
- The XC 550/560 Integrated Fiery Color Server must be at version 1.0 prior to performing this install. This software is supplemental to the 1.0 launch software.
- Ensure the following patches are installed in the order they are listed here before installing this patch.
 - 1-16C6H7

Installation Instructions

NOTE: The customer or a member of the Xerox Service Team may install this software.

Integrated_550_560_SP1.1.ps:

Before upgrading the software, ensure there are no other jobs processing.

1. Import the patch file Integrated_550_560_SP1.1.ps with Command Workstation to the **Direct** queue.
2. You must wait at least 5 minutes after importing the patch file before rebooting the system. This will ensure the patch file is completely processed.
3. From Command Workstation, select **Server > Reboot Server**. The Fiery will reboot.
4. Wait until the Fiery has come to idle and print out the configuration page.
5. Verify the **Update Info** section. It should contain the patch number SP1.1

6. Under the **Update Info** section of the configuration page, look for SP1 and any patches listed after SP1.
 - If SP1 is not listed on the configuration page, no action is required.
 - If SP1 is listed **and** there are also additional patches listed between SP1 and SP1.1 (other than composite patch 1-16C6H7), you must re-install those patches.

CAUTION: Failure to reinstall post-SP1 patches after installing SP1.1 will result in a loss of the SPAR fixes from those patches and may introduce additional side effects.