

Kit Installation Instructions

PSG SPAR Team

Product(s):	DocuColor 250/240 bustled Fiery color server v1.2	Date:	08/27/08
Title:	Patch 1-YNN0J Installation instructions	Page:	1 of 1

Purpose

This software kit provides a version 1.2 software update in response to a DocuColor 250/240 bustled Fiery color server SPAR. Refer to the included customer letter for more information.

In the event of a version 1.2 system reinstall this software should be reapplied.

Kit Contents

Qty.	Description
1	Kit Installation Instructions
1	Customer Letter
1	Patch 1-YNN0J.ps

Prerequisites

- Previous working knowledge with the DocuColor 250/240 bustled Fiery color server.
- The DocuColor 250/240 bustled Fiery color server must be at version 1.2 prior to performing this install. This software is supplemental to the version 1.2 launch software.
- The following patch must be loaded prior to installing this patch. It available via System Updates or www.xerox.com.
 - 1-XVE1A

Installation Instructions

Note: This patch is Exclusive which means it must be installed independently and the server rebooted/restarted once. After which, other patches can be applied to the server.

- ___ 1. Import the patch file **1-YNN0J.ps** with Command Workstation to the **Direct** queue.
- ___ 2. You must wait at least 60 seconds after importing the patch file before rebooting the system. This will ensure the patch file is completely processed.
- ___ 3. From Command Workstation, select **Server > Reboot Server**. The Fiery will reboot.
- ___ 4. Wait until the Fiery has come to idle and print out the configuration page.
- ___ 5. Verify the **System Update Log**. It should contain the patch number **1-YNN0J**.