Product Enhancement Document WorkCentre 3335/3345 Firmware 60.005.00.000

Release Date: May 10, 2019

dc19rn3860

Software Release Details

Component	Version
System	60.005.00.000
MCB	V2.50.05.00
Engine (IOT)	V0.00.39_V1.00
Network	4.00.50.75
Link to Software	[WC3335 / WC3345](#)

I.   Fixes/Features new in this release

- Introduced Firmware to change the belt motor's travel profile to reduce the impact on the timing belt drive feature.

II.   Installation Notes

Install instructions are included in the zip file containing firmware. Unzip and download before attempting to install the firmware