Customer Release Notes
Phaser® 3635MFP
General Release 20.105.01.007

Release Date: January 2, 2013
dc12rn3076crn

Software Release Details

Component	Version
System Software	20.105.01.007
Main Controller	1.05.01.07
IOT	1.00.34
User Interface	0.035.28.032
Network Controller	4.05.05

Important

Once this digitally signed release is installed, the machine CANNOT be downgraded to a non-digitally signed release. Releases less than v20.105.01.004 are NOT digitally signed.

Caution

The Machine Self Signed Digital Certificate minimum key size has increased to 1024 bit. If at the time of installing this release the device's Self Signed Digital Certificate key size is less than 1024 bit the admin may have to use a browser other than Microsoft Internet Explorer to access the device's CWIS page in order to create a Self Signed Digital Certificate that is at least 1024 bit. Due to a Microsoft Windows security update Microsoft Internet Explorer may not open https pages with a digital certificate of less than 1024 bits.

Purpose

This release provides the following enhancement:

- A fix has been developed for the following issue: With various Secure Access solutions enabled, intermittently the local UI will lockup and display a hash pattern, or may reboot when releasing print jobs.
- Machine Self Signed Digital Certificate minimum key size increases to 1024 bits
- Provides the ability to lock down the device's Web User Interface behind the Admin password
- Includes the ability to remotely configure scanning parameters for email and repository
- Now able to set copier and printer defaults using the device's Web User Interface
- The Local User Interface icons are now able to be hidden
- Improved template pool functionality
- The Secure Access screen now appears when the Secure Access session ends.
- The Software Upgrade Enable/Disable Setting now appears on the Configuration Report
- Software upgrades can now be configured via SNMP

- Improved Fax functionality
- Can now set the language field on the device's local user interface keyboard, and the System Timeout Timer using Xerox Device Manager
- Improved Secure Access and Job Based Accounting functionality
- The device is now compatible with version 3 of the 802.1x standard
- Improved speed when authenticating with Secure Access
- Improved EIP (Xerox Extensible Interface Platform®) reliability
- Improved Auto Tray switching
- Mixed size original scans are now scaled correctly.
- Now able to enable Immediate Image Overwrite via the device's webpage.

  Note: This can be done by going to the Properties tab → Security → Image Overwrite → Immediate Image Overwrite
- Improved connectivity with NetWare® print server.
- Improved Equitrac Office® interaction
- Now able to place an underscore at the beginning of an email address
- Scanning over SMB to a share on a virtual node in a Windows Server® 2008 cluster now works

Software Release Details

Software is available from

http://www.support.xerox.com/support/phaser-3635mfp/downloads/

© 2013 Xerox Corporation. All Rights Reserved. XEROX®, XEROX and Design®, Phaser®, and Xerox Extensible Interface Platform® are trademarks of Xerox Corporation in the United States and/or other countries.

Equitrac Office® is a registered trademark of Equitrac Corporation.

Netware® is a registered trademark of Novell, Inc., in the United States and other countries.

Windows Server® is a registered trademark of Microsoft Corporation in the United States and/or other countries.