XC 550/560 Integrated Fiery Color Server

October 2012

Dear Xerox XC550/560 Integrated Fiery Color Server customer:

Your XC 550/560 Integrated Fiery Color Server can now be upgraded with the **1.1sp4** software patch.

NOTE: Your system must be at version 1.1, sp1 sp2 and sp3 prior to installing this software.

We tested this software patch specifically for the System Problem Action Requests (SPARs) noted below. If your SPAR number is not listed, we are providing you this software either because you reported a problem that resembles one of the listed fixes or because our testing has shown that this software should resolve your problem. If this software does not resolve your problem, please contact the hotline and provide a detailed job scenario and sample job(s) for further investigation, testing, and resolution.

This software patch contains fixes for the following SPARs:

SPAR #		Description
1.	108624506	Fiery requests 295x200 (7.9 x11.6 inch) Custom Paper Size instead of A4 Paper Size for a particular file
2.	207132489	Fiery proxy will not allow special character password
3.		Fiery crashes when domain name is more than 32 characters

-

NOTE: Not all child SPARs will be listed in this letter.

Prerequisites:

1.1sp1

1.1sp2

1.1sp3