Patch Installation Instructions

Product(s): Xerox Color 550/560 CX550/560 v2.0	Date: 01/04/12
Title: XCRef319_Patch Installation Instructions	Page: 1 of 1

Purpose

This software patch provides a 2.0 software update in response to a Xerox Color 550/560 CX550/560 v 2.0 SPAR. Refer to the included customer letter for more information.

In the event of a 2.0 system reinstall this software should be reapplied.

Kit Contents

Qty.	Description
1	Patch Installation Instructions
1	Customer Letter
1	XCRef319_patch.exe

- Previous working knowledge with the Xerox Color 550/560 CX550/560 v 2.0.

- The Xerox Color 550/560 CX550/560 must be at 2.0 version prior to performing this install. This software is supplemental to the 2.0 launch software.

Installation Instructions

NOTE: The customer or a member of the Xerox Service Team may install this software.

XCRef319_patch:

Before upgrading the software, ensure there are no other jobs processing.

__ 1. Quit the Creo Spire CX550/560 color server workspace. Ensure that the taskbar icon disappears.

__ 2. Double-click the XCRef319_patch_for_CX560_v2.0.exe file to install the patch.

__ 3. Start the Creo Spire CX550/560 color server software.

__ 4. Verify that the patch was installed successfully:

    __ a. From the **Help** menu, select **About**.

    __ b. In the **Updates** box, ensure that Line_patch appears.