XC 550/560 Integrated Fiery Color Server

February 2013

Dear Xerox XC550/560 Integrated Fiery Color Server customer:

Your XC 550/560 Integrated Fiery Color Server can now be upgraded with the **1.1sp5** software patch.

NOTE: Your system must be at version 1.1, sp1 sp2, sp3 and sp 4prior to installing this software.

We tested this software patch specifically for the System Problem Action Requests (SPARs) noted below. If your SPAR number is not listed, we are providing you this software either because you reported a problem that resembles one of the listed fixes or because our testing has shown that this software should resolve your problem. If this software does not resolve your problem, please contact the hotline and provide a detailed job scenario and sample job(s) for further investigation, testing, and resolution.

This software patch contains fixes for the following SPARs:

SPAR #		Description
1.	112805239	Not able to use scan network using SMB with OS 10.7 or 10.8
2.	654852262	"Internal error: Unknown Error" when processing certain PDF files from InDesign.
3.	174556020	Internal error: "Unknown Error" when processing certain PDF files from PowerPoint 2010
4.	763135646	Mesh object with Pantone spot color will be printed on every page in Illustrator's Host-Based Separation
5.		Cannot print Fiery PS Font List, authentication error occurs

Other fixes included:

- **1-1HK486 - DMP/AirPrint not functional with Apple iOS6**
- **1-1IMBWP- network SMB scanning to windows 2012 server generates 0 byte files.**

NOTE: Not all child SPARs will be listed in this letter.

Prerequisites:

1.1sp1

1.1sp2

1.1sp3

1.1sp4