XEROX

DocuColor 250/240

February 2008

Dear Xerox DocuColor 250/240 Customer:
Your DocuColor CX250 color server can now be upgraded with the enclosed Tray6-Patch. Please read the enclosed documentation regarding your SPAR software prior to installation. Included are the Release Notes, which list detailed installation instructions, prerequisites and any known limitations.

This updated software release was tested to specifically resolve the System Problem Action Requests (SPARs) noted below. Some SPAR numbers may not appear on the list if there were multiple customers who submitted SPARs for the same problem. If your SPAR number is not listed, Xerox is providing you this software in an attempt to resolve a reported problem that may resemble one of the listed fixes. Should this software fail to resolve your problem, Xerox will require a detailed job scenario and sample job(s) for further investigation, testing, and resolution. *Any new problems that arise from installing this software must be addressed in a new SPAR.*

PREREQUISITE: *CX250_v1.1_SP2.*

NOTE: *This patch supersedes the previously released 12x18-Booklet_Patch.*

This SPAR CX250 patch will address the following SPARs:

	SPAR	Problem Description
1.	**015982057**	Tray 6 out of place after Sleep mode.
2.	**027361842**	Unable to print 13x19 jobs from tray 6 after installing SP2.
3.	**184690858**	Unable to print 12x18 jobs from tray 6 after installing SP2.
4.	**545652552**	Cannot print several booklets at the same time.

NOTE: *Not all child SPARs will be reflected in this document.*

Thank you,

Xerox Corporation
800 Phillips Road
Webster, NY 14580

Release Notes

PATCH: TRAY6-PATCH

PRODUCT: CX250 FOR DC250/240

PREREQUISITE(S): CX250_v1.1_SP2@19-NOV-2007

INSTALLATION INSTRUCTIONS

1. Quit the Spire CX250 application. Verify that the Spire CX250 color server icon has disappeared from the launch bar in the system tray.

2. Copy Tray6-Patch.exe to the Spire desktop, and then double-click to install.

3. Follow the steps in the Installation Wizard. When prompted, click **Finish** to exit the wizard.

4. Restart the system by clicking **Start** > **Shutdown** > **Restart**.

5. After the system restarts, the Spire CX250 software will launch automatically.

6. To verify that the patch was successfully installed, go to the **Help** menu, select **About**, and confirm that the **Tray6-Patch** is listed next to **Updates**.

NOTE: *This patch supersedes the previously released 12x18-Booklet_Patch.*

LIMITATIONS

None