EFI Fiery™ for the Xerox® EX-i C60/C70 Color Server

Fiery Driver release note

Overview

This checklist will help you prepare for the installation of **FIT100878861.zip**

General Information	
○ Current Version	1.0
○ Defect ID	FIT100878861
○ Release Date	10-February-2015
○ Files included	FIT100878861.zip
○ File size	185897503 bytes
○ Checksum	2426711432

Issue(s) addressed with this release

- **FIT100878861: Fiery Driver for EXi C60-C70 Printer Server Powered by Fiery.**

- FIT100878861: Printer default value is wrong for GCR when configure is set as "OFF"

- FIT100878863: Xerox GCR value is shown as ON in PS driver, when Xerox GCR is OFF in configure.

- FIT100878860: There should be 3 values for Xerox GCR (Printer's Default, On and Off) in Ps Driver. The default should be Printer default (same like resolution key)

- FIT100878865: GCR value is getting set to OFF on relaunching the JP with the GCR value set to ON

- FIT100868639: Unable to print Tab stock from internal trays.

Steps to reproduce the issue(s)

- **FIT100878861: Printer default value is wrong for GCR when configure is set as "OFF"**

1. Launch Fiery configure

2. Change the GCR setting to OFF from Fiery Configure → RIP → PS → GCR.

3. Install EXi C60-C70 print driver on any Windows Client

4. Open any document and launch job properties.

5. Check the Xerox GCR value from Properties → Color tab.

EFI Fiery™ for the Xerox® EX-i C60/C70 Color Server

Fiery Driver release note

Result: Xerox GCR is ON.

- **FIT100878863: Xerox GCR value is shown as ON in PS driver, when Xerox GCR is OFF in configure.**

1. Launch Fiery configure.
2. Change the GCR setting to OFF from Fiery Configure → RIP → PS → GCR.
3. Install EXi C60-C70 print driver on MAC 10.9.2
4. Open any document and launch job properties.
5. Check the Xerox GCR value from Properties → Color tab.

Result: Xerox GCR is ON.

- **FIT100878860: There should be 3 values for Xerox GCR (Printer's Default, On and Off) in Ps Driver. The default should be Printer default (same like resolution key)**

1. Launch Fiery configure
2. Change the GCR setting to OFF from Fiery Configure → RIP → PS → GCR.
3. Install EXi C60-C70 print driver on any Windows Client
4. Open any document and launch job properties.
5. Check the Xerox GCR value from Properties → Color tab.

Result: Printer's Default option under Xerox GCR is missing

- **FIT100878865:GCR value is getting set to OFF on relaunch of JP with the GCR value set to ON**

1. Launch Fiery configure
2. Change the GCR setting to OFF from Fiery Configure → RIP → PS → GCR.
3. Install EXi C60-C70 print driver on any Windows Client
4. Open any document and launch job properties.
5. Check the Xerox GCR value from Properties → Color tab.
6. Click on "OK"
7. Again click on properties and check the Xerox GCR value

Result: Xerox GCR option is unchecked

EFI Fiery™ for the Xerox® EX-i C60/C70 Color Server

Fiery Driver release note

IMPORTANT

Before installing FIT100878861.zip

1. Known issues listed below, read before installing **FIT100878861.zip**

- **This driver obsoletes previous drivers : FIT100868639**

2. Components versions included in this package:

   Windows

   - UI version: 4.6.006.0

   - JP version: 2.6.0.029

   MAC

   - JP version: 2.6.0.029

   - Plug-in version: 3.61.012.0

Windows Driver installation instructions

1. Uninstall any previous driver using Printer Delete Utility.

2. Reboot the client.

3. Unzip **FIT100878861.zip** file.

4. Double click on **FIT100878861** folder. Execute *printdrv.exe* executable file and click *Install*.

5. Install the driver on the client and add printer.

Mac Driver installation instructions

1. Uninstall any previous driver using Fiery Software Uninstaller.

2. Reboot the Mac

3. Unzip **FIT100878861.zip** file.

EFI Fiery™ for the Xerox® EX-i C60/C70 Color Server

Fiery Driver release note

4. Double click on **FIT100878861** folder.

5. Execute the Fiery Printer Driver.dmg file.

6. Install the driver on the Mac