General Release Notes
Xerox® Global Print Driver® V3
Version 5.1035.2.0

Release Date: December 27, 2024   **dc25rn1111**

I. Software Release Details

PS (WHQL)	
[32 BIT](#)	[64 BIT](#)
PCL6 (WHQL)	
[32 BIT](#)	[64 BIT](#)

II. Fixes/Features new in this release

- Various bug fixes
- Products added to GPD

    - Xerox® AltaLink C8230 Color MFP
    - Xerox® AltaLink C8235 Color MFP
    - Xerox® AltaLink C8245 Color MFP
    - Xerox® AltaLink C8255 Color MFP
    - Xerox® AltaLink C8270 Color MFP
    - Xerox® AltaLink C8245 MFP
    - Xerox® AltaLink C8255 MFP
    - Xerox® AltaLink C8270 MFP
    - Xerox® PrimeLink C9265 Printer
    - Xerox® PrimeLink C9275 Printer
    - Xerox® PrimeLink C9281 Printer

III. Additional Documentation

- To obtain the latest XML Editor documentation please use the following link:
    - http://www.office.xerox.com/latest/SFTHT-01U.pdf
- To obtain the latest Device Compatibility Pack (DCP) documentation please use the following link:
    - http://www.office.xerox.com/support/dctips/dc11cc0482.pdf
    - **Note:** There are no new DCPs for this version of the X-GPD.
- To obtain the latest White Paper for Xerox Global Print Driver please use the following link:
    - Xerox V3 and V4 Print Driver Platforms Overview - Xerox Global Print Driver - Xerox

To obtain the Product Enhancements Document
https://www.support.xerox.com/support/globalprintdriver/file-download/enca.html?contentId=**169497**

IV. Installation Notes

Please refer to the following V3 Xerox Print Driver installation instructions:

- V3 Link: http://download.support.xerox.com/pub/docs/GLOBALPRINTDRIVER/userdocs/any-os/en_GB/GPD_V3_Install_Guide_071019.pdf

V. Open Escalation

The following list contains escalations that are currently being investigated by development. Final disposition of these escalations has not yet been determined. This list is for information purposes only and does not imply any specific solution will be provided.

- None

VI. Fixes/Features from previous releases

Some of these solutions may require special installation or setup instructions, which will be described in *"Caveats for Specific SPARs"* section.

Please contact your local support center to request the product specific print driver.

SPAR / SFR #	Fixed in release	PDL / APP	V3 / V4	Description	OPCO
1470918	5.1009.2.0	NA	V3	XWC- XML defaults not applying	Americas
NA	5.1009.1.0	NA	V3	Products added To GPD: • Xerox C325 Multifunction • Xerox C320 Color Printer	NA
1466917	5.979.3.0	NA	V3	Customer is not able to select hole punch option in the print driver when paper size is selected as A5 with BR finisher attached.	EMEA
NA	5.979.3.0	NA	V3	Infrastructure fixes for issues identified during security scans.	NA
NA	5.979.3.0	NA	V3	Upgrade to OpenSSL 3.0.11	NA
NA	5.979.3.0	NA	V3	The following products have been added to the GPD; Xerox VersaLink C620 Xerox VersaLink B620 Printer	NA
1464559	5.951.9.0	NA	NA	V4 Driver: Prints a 4mm Page Reduction - V3 Driver: Unable to Print 2 Watermarks with Driver.	Americas
1465277	5.951.9.0	NA	NA	Chinese folders are getting created after installing the latest GPD driver version 5.919.500.0.0	Americas
NA	5.951.9.0	NA	NA	Support for ARM 64 architecture.	NA
NA	5.951.9.0	NA	NA	The following devices were added to the GPD • Xerox C410 Color Printer Xerox B410 Printer	NA
1461517	5.919.4.0	NA	NA	Customer facing issue with 11*17-page color printing in Primelink C9070 device	Xerox Internal

1461168	5.919.4.0	NA	NA	After changing the Preset from the dropdown, the Preset name is not getting reflected correctly.	EMEA
1456306	5.919.4.0	NA	NA	User intermittently receives (016-757) Invalid User when releasing jobs from XWS.	Americas
1462134	5.919.4.0	NA	NA	X3txt01X.dll files are not digitally signed for XGPD PS/PCL driver	EMEA

NA	5.919.4.0	NA	NA	The following devices were added to the GPD
				   o VersaLink B625
				   o VersaLink C625
					NA

1460342	5.887.3.1	NA	NA	Print jobs spool to 80GB and crashes the XWS server	EMEA
NA	5.887.3.0	NA	NA	The Adaptive Learning (Suggestions) feature was added. Adaptive Learning provides a user with suggestions on 1-Touch / Preset creation and default settings based on analysis of the user's past usage. The feature is meant to reduce repetitive/complex changes in driver print preferences.	NA
NA	5.887.3.0	NA	NA	Permissions Tab has been removed.	NA
1451869	5.860.1.0	PS/PCL6	NA	Driver Slow performance issue when Share Diagnostic Data is Enabled in Driver.	EMEA
NA	5.860.1.0	PS/PCL6	NA	The following device was added to the GPD 'Xerox C310 Color Printer' Xerox® B305 MFP, Xerox®B315 MFP , Xerox® C310 Color Printer, Xerox® C315 Color MFP, Xerox® VersaLink B7125 MFP, Xerox® VersaLink B7130 MFP, Xerox® VersaLink B7135 MFP, Xerox® VersaLink C7120 Color MFP, Xerox® VersaLink C7125 Color MFP, Xerox® VersaLink C7130 Color MFP	NA
NA	5.860.1.0	PS/PCL6	NA	The following Fuji devices were added to the GPD; ApeosPort C7070/C6570/C5570/C4570/C3570/C3070 ApeosPort C2360/C2060	NA
1454462	5.810.8.3	PS/PCL6	NA	GPD not change back to customer default after switching back to color.	108867
NA	5.810.8.3	PS/PCL6	NA	Printer connection error after installing Microsoft August 2021 Security Update - this release addresses the 'Connect to Printer - Windows cannot connect to the printer (0x0000002A or error 0x000003e3)' seen when connecting to a new network print queue. It also resolves the error 'The RPC server is unavailable and/or StartDocPrinter' seen when a network print queue requires a driver update.	NA
1453008	5.810.8.0	PS/PCL6	NA	Incorrect Russian translation in driver	Russia

NA	5.810.8.0	PS/PCL6	NA	The following devices were added to the X-GPD: Xerox® EC8036 Xerox® EC8056 Xerox® B230 Printer Xerox® B225 Multifunction Printer Xerox® B235 Multifunction Printer Xerox® C230 Color Printer Xerox® C235 Color Multifunction Printer Xerox® B310 Printer	NA
NA	5.810.8.0	PS/PCL6	NA	The following Fuji devices were added to the X-GPD: Fuji Xerox ApeosPort C2060 Fuji Xerox ApeosPort C2060 for Japan Fuji Xerox ApeosPort C2360 for Japan Fuji Xerox ApeosPort C2560 Fuji Xerox ApeosPort C2570 for Japan Fuji Xerox ApeosPort C3060 Fuji Xerox ApeosPort C3070 Fuji Xerox ApeosPort C3070 for Japan Fuji Xerox ApeosPort C3570 Fuji Xerox ApeosPort C3570 for Japan Fuji Xerox ApeosPort C4570 Fuji Xerox ApeosPort C4570 for Japan Fuji Xerox ApeosPort C5570 Fuji Xerox ApeosPort C5570 for Japan Fuji Xerox ApeosPort C6570 Fuji Xerox ApeosPort C6570 for Japan Fuji Xerox ApeosPort C7070 Fuji Xerox ApeosPort C7070 for Japan	NA
1451711	5.759.5.3	PS/PCL6	NA	USB-connected 3345: DADF scan of A4 produces A5-size result with cropped image **Scan to Desktop App must be downloaded from the Microsoft store.**	Russia
1452484	5.759.5.3	PS/PCL6	NA	Adobe DC or Reader 2017 loses paper size list after first printing when a custom paper name has been added in the XGPD	Austria
1417049	5.759.5.0	PS/PCL6	NA	Syntax Error when printing customer's PDF file, using the X-GPD (PS and PCL) when the Model is set to a Fuji Xerox Product.	FX IBG - Asia Pacific
1417380	5.759.5.0	PS/PCL6	NA	Xerox print driver is copying files from the C:\ driver into the Xerox print driver folder within the customer's Citrix environment	US - XOG
NA	5.759.5.0	PS/PCL6	NA	One Touch Presets	NA
CQGbl01417380	5.733.11.5	PS/PCL6	NA	Xerox print driver is copying files from the C:\ driver into the Xerox print driver folder within the customer's Citrix environment	US - XOG
CQGbl01417049	5.733.11.5	PS/PCL6	NA	Syntax Error when printing customer's PDF file, using the X-GPD (PS and PCL) when the Model is set to a Fuji Xerox Product.	FX IBG - Asia Pacific
CQGbl01400950	5.733.11.1	PS/PCL6	NA	Customer's Custom Media Types are not being saved when selected as the Media type for Special Pages.	XE France
CQGbl01362674	5.733.11.0	PS/PCL6	V3	Unable to default regular print jobs to the finisher output tray. The only way a job will go to the finisher is if it is stapled.	US - XOG
CQGbl01392830	5.733.11.0	PS/PCL6	V3	A low-privileged interactive user can abuse Cirrato's printer installation mechanism with X-GPD	US - WVDS
NA	5.733.11.0	PS/PCL6	V3	The following Fuji Xerox devices have been added to this GPD release:	NA

				• Fuji Xerox ApeosPort-VII C3372 for Japan • Fuji Xerox ApeosPort-VII C5588 • Fuji Xerox ApeosPort-VII C5588 for Japan • Fuji Xerox ApeosPort-VII C6688 • Fuji Xerox ApeosPort-VII C6688 for Japan • Fuji Xerox ApeosPort-VII C7788 • Fuji Xerox ApeosPort-VII C7788 for Japan • Fuji Xerox DocuCentre-VII C3372 for Japan • Fuji Xerox DocuCentre-VII C5588 • Fuji Xerox DocuCentre-VII C5588 for Japan • Fuji Xerox DocuCentre-VII C6688 • Fuji Xerox DocuCentre-VII C6688 for Japan • Fuji Xerox DocuCentre-VII C7788 • Fuji Xerox DocuCentre-VII C7788 for Japan	
NA	5.733.11.0	PS/PCL6	V3	The following Xerox devices have been added to this GPD release: • Xerox AltaLink C8130 • Xerox AltaLink C8135 • Xerox AltaLink C8145 • Xerox AltaLink C8155 • Xerox AltaLink C8170 • Xerox AltaLink B8145 • Xerox AltaLink B8155 • Xerox AltaLink B8170 • Xerox PrimeLink B9100 • Xerox PrimeLink B9110 • Xerox PrimeLink B9125 • Xerox PrimeLink B9136	NA
CQGbl01367861	5.703.12.4	PS/PCL6	V3	Secure Print Only feature malfunctions when using Cirrato print management to implement it	US - DISC
CQGbl01365699 CQGbl01366033	5.703.12.2	PS PCL6	V3	Global Print Driver (GPD) PCL6 v3 Print driver is using the wrong Job Owner ID when printing documents from client workstations when logged on with a Dual-Persona CAC	US - DISC
CQGbl01346651	5.703.12	PS PCL6	V3	All copies of Booklet stapled together during first print job	XE - France
CQGbl01348932	5.703.12	PS PCL6	V3	XSA print time prompt options greyed out using V3 XGPD PS or PCL6 v5.675.6.0	XE - France
CQGbl01346857	5.703.12	PS PCL6	V3	Driver issue -translation of "imposition source" is wrong if driver is set to danish (expected "layout kilde")	XE - France
n/a	5.703.12	PS PCL6	V3	The following devices were added to the X-GPD: • Xerox Baltoro HF Inkjet Press • Xerox PrimeLink C9065 • Xerox PrimeLink C9070	n/a
CQGbl01338462	5.675.6.3	PS PCL6	V3	When switching from Envelope to Letter (size jobs), within Word, the device displays "The Selected Paper is Unavailable" with the error code 77-967 prompting to load "Letter (8.5 x 11), Envelope, White" after successfully printing the Envelope job.	US - DISC
CQGbl01337789	5.675.6.3	PS PCL6	V3	With the Versalink B600/B610/B605 and B615 drivers it is not possible to select paper types in the WORD page setup section.	XE - France
CQGbl01331833	5.675.6	PS PCL6	V3	Norwegian translation error in paper type.	XE - France

CQGbl01334121	5.675.6	PS PCL6	V3	Printing Mixed Sized PDF Duplexed Stapled causes Tabloid to rotate upside down Special Instructions: Postscript passthrough must be disabled.	US - DISC
CQGbl01335909	5.675.6	PS PCL6	V3	This is the follow up from CQGbl01333845, but against WC6605 and all products there is no BW Synchro option.	XE - France
CQGbl01336717	5.675.6	PS PCL6	V3	Machine cannot print auto duplex lightweight glossy cardstock, but can copy.	CAN - COEN
CQGbl01330429	5.645.5.7	PS PCL6	V3	Printer properties extremely slow to populate when using the XWC client and associated GPD	XE - France
CQGbl01333461	5.645.5.7	PS PCL6	V3	Slow printing performance when trying to open printer properties.	US - DISC
CQGbl01328455	5.645.5.7	PS PCL6	V3	Driver version 5.617.7 and higher are producing 16000+ SIDS lookup requesting information to the Active Directory, each time an end user selects print.	XE - France
CQGbl01309368	5.645.5.5	PS PCL6	V3	When Excel's Print Quality is set to 1200dpi, the customer's printed images are enlarged 200%; shifted down and to the right on the page; causing image Loss.	XE - France
CQGbl01320128	5.645.5.3	PS PCL6	V3	After downloading the GPD from XPMMS CLOUD and installing the defaults of the driver are not been honored within applications.	XE - France
n/a	5.617.7.0	PS PCL6	V3/V4	Added SysObjectID support to the following models in the X-GPD: Xerox B1022 Multifunction Printer Xerox B1025 Multifunction Printer	n/a
CQGbl01302852	7.48.18.0 7.72.0	Desktop App PS PCL6	V4	Microsoft Custom Paper Size Forms are incorrectly displayed with the Xerox GPD (v3 and v4) drivers.	XE - France
CQGbl01257393	7.48.9.0 7.59.0.0	Desktop APP PS PCL6	V4	Unable to Successfully Use Quick Print Feature in Google Chrome to Change from Color to Black and White When Printing	US - WVDS
CQGbl01294631	5.617.7.0	PS PCL PCL6 V3	V3	Within Office 2016 and particularly Word 2016 there is an excessive delay when switching between print queues (App-V)	XE - France
n/a	5.617.17.0	PS PCL PCL6	n/a	The Stringed version of this release and future releases of the V3 X-GPD will now be "Xerox GPD <PDL> <Driver Version> (ex: Xerox GPD PCL6 V5.617.7.0) The change was made to prevent confusion between the V4 architecture Global Print Driver and the V3 architecture Global Print Driver.	n/a
CQGbl01227486	5.585.13.9	PS PCL5 PCL6	n/a	After update from Citrix Xen App 6.5 to 7.15, tray selection in UPD driver is not ported to Xerox XGPD	XE - France
CQGbl01254859	5.585.13.8	PS	n/a	Users cannot override Application Saved settings when they change settings such as # of copies, staple, collate, and duplex in an application print dialog. This can lead to undesired behavior in when printing and is a regression from 5.548.8.	US - DISC
CQGbl01195020	5.585.13.3	PS PCL5 PCL6	n/a	Incorrect UserID when driver switch to non-English mode	US - WVDS
CQGbl01197096	5.585.13.3	PS PCL5 PCL6	n/a	In both the CQ 8570 (Taipan Plus) and CQ 8580 (Adder) drivers, after 5.273.21 the 'margins' feature was removed. The customer relies on this feature being set to	FX IBG - Asia Pacific

				'none' to get their forms to print without truncation on 3x5" media.	
CQGbl01150306	5.585.13	PS PCL5 PCL6	n/a	When toggling between printers from an application, the Xerox Global Print Driver takes longer to load than others.	US - DISC
CQGbl01110198	5.585.13	PS PCL5 PCL6	n/a	Long submission time with Global Print Driver through Finnova	XE - France
CQGbl01169850	5.585.13	PS PCL5 PCL6	n/a	The driver becomes progressively too slow on Citrix 2016 server	XE - France
CQGbl01182108	5.585.13	PS PCL5 PCL6	n/a	Slow printing with Oracle AutoVue applet	US - DISC
CQGbl01171550	5.585.13	PS PCL5 PCL6	n/a	LDAP mechanism of driver malfunctioning	US - DISC
CQGbl01148374 CQGbl01158103 CQGbl01168230 CQGbl01152167	5.548.8.2	PS PCL5 PCL6	n/a	Squarefold Trimmer issue	XE-France CAN-COEN
CQGbl01146320	5.548.8.2	PS PCL5 PCL6	n/a	When use Saved Setting template in the Global Driver for FFPS, it overrides Copies count value to 1	FX IBG - Asia Pacific
n/a	5.548.8.0	PS PCL5 PCL6	n/a	Added SysObjectID support to the following models in the X-GPD: Xerox Versalink C7000, 7020/7025/7030 Xerox Versalink B600/B605, B610/B615 Xerox Versalink C500/C505, C600/C605 Xerox Versalink B7025/B7030/B7035 Xerox Versalink C400/C405 Xerox Versalink B400/B405 Xerox Altalink B8045/B8055, B8065/B8075/B8090 Xerox Altalink C8030/C8035, C8045/C8055/C8070 Xerox Versant 180 Press Xerox Versant 3100 Press	n/a
CQGbl01120614	5.548.8	PS PCL5 PCL6	n/a	Print driver settings not consistent with "saved settings" applied to application like Word	XE - France
CQGbl01139998	5.548.8	PS PCL5 PCL6	n/a	When using XML tools to preconfigure driver unable to print 1 sided	US - DISC
CQGbl00998337 1	5.520.6	PS PCL5 PCL6	n/a	XGPD v5.496.7.0 Booklet not printing when using Word 2013 on ApeosPort V C7785	FX IBG - Asia Pacific
CQGbl0102160 8	5.520.6	PS PCL PCL6	n/a	Disable job notification does not stay disabled when installing from Server to Client	US - WVDS
CQGbl0092508 4	5.496.7.6	PS PCL5 PCL6	n/a	LDAP phonebook for LanFax doesn't work. Caveats and Special Notes 1. The print driver will only search the 'LDAP Phone Book' using the Common Name (cn). The print driver will not search on the Surname (sn). 2. If a user does not have a Fax Phone Number populated within Active Directory the user will not appear in the 'Search Results' within the print driver. 3. The wild card character (*) may be used when performing an LDAP search within the print driver 4. The LDAP Server type, under LDAP Mappings will always show "Other". This is a limitation of the device. Currently the device does not send the LDAP Server Type as part of the LDAP information via XBDS.	XE-France

CQGbl00901535	5.496.7.6	PS PCL5 PCL6	n/a	Margin borders are cutoff when printing with PCL6 driver to the WC57xx from MSWORD		CAN-COEN
n/a	5.496.7.0	PS PCL5 PCL6	n/a	Added SysObjectID support for the Xerox Brenva HD Production Inkjet Press in the X-GPD.		n/a
CQGbl00875112	5.469.10.8	PS PCL5 PCL6	n/a	Latest XGPD version 5469.900.0.0 CRASHED when Enable Color Access Control & Color Access Group(s) on Win2008 and Win2012R2 Server.		FX IBG-Asia Pacific
CQGbl00879271	5.469.10.8	PS	n/a	Inconsistent results printing 11x17 PDF - Image Scaling		US-DISC
CQGbl00893771	5.469.10.8	PS PCL5 PCL6	n/a	Excel 2010/2013 crashes if GPD is configured to use a local NUL port. Customer is using PaperCut solution.		XE-France
CQGbl00905468	5.469.10.8	PS PCL6	n/a	Win Explorer crashes when using XGPD with color access control.		XE-France
CQGbl00895337	5.469.10.5	PCL6	n/a	Sporadically prints only thin strip of image from Windows Photo Viewer.		XE-France
CQGbl00845506	5.469.10.5	PS PCL6	n/a	The stapling options in Word give us wrong information about how the staples are placed.		XE-France
304356	5.469.10.5	PS PCL6	n/a	SFR: Rotate Image 180 setting configurable using the XML tool for PCL6 XGPD Configuration Steps: 1.Configure XML Tool 3.7.7: for the following devices: WC58XX, WC59XX, WC72XX, WC78XX and CQ9330 2. Configure the following features within XML: a. Disable "Intelligent Rotation" b. Adjust the "Subsequent Rotation" settings to control the output 3. Save the XML configuration file.		CET
CQGbl00855696	5.469.10.5	PCL5	n/a	Unable to duplex if job contains mixed letter/portrait pages		XE-France
n/a	5.469.9.0	PS PCL5 PCL6	n/a	• There were no fixes made to Office Products supported within this version of X-GPD. • There were two changes made to the Named Paper feature which appears in the Production Products. • There was one change to an SMB device which impacts duplexing jobs with different orientations		n/a
n/a	5.469.9.0	PS PCL5 PCL6	n/a	The Windows XP and Windows 2003 Xerox Global Print Driver (XGPD) driver links on Xerox.com will no longer be updated with new drivers. The XGPD Release (v5.469.9) will be available until further notice.		n/a

The following products are Only supported in Basic Mode.
They are no longer listed in the Configuration dropdown (Printer Properties – Administration tab).
Note: This list will be updated when additional devices are removed.

Products					
WC2128	CC 40	CC WCWCP 65	Phaser 3300 MFP	Phaser 8500	4112 EPS
WC2636	CQ 9201	CC WCWCP 75	WCC2424	Phaser 8550	4127 CP
WC3545	CQ 9202	WC5135	Phaser 7400	DC 5000	4127 EPS
WC7232	CQ 9203	WC5632	Phaser 7750	DC 7000	Xerox WorkCentre 4250
WC7242	CC WCWCP 232	WC5638	8400	x700	Xerox WorkCentre 4260
WC7655	CC WCWCP 238	WC5645	Phaser 8400	DC 8000	DMP and FFPS Models Xerox Color 550 Xerox Color 560

					Xerox Color 570
WC7665	CC WCWCP 245	WC5655	Phaser 6300	6135U	Xerox WorkCentre 3550
WC7675	CC WCWCP 255	WC5665	Phaser 6350	6180U	Xerox Phaser 4600
WC7425	CC WCWCP 265	WC5675	WC2424DN	DP 180IPS	Xerox Phaser 4620
WC7430	CC WCWCP 275	WC5687	WC2424DP	DP 180LPS	Xerox Phaser 3635MFP
WC7435	WC5030	CC WCWCP 165	WC2424DX	DP 180MXIPS	Xerox WorkCentre 7755 Xerox WorkCentre 7765 Xerox WorkCentre 7775
P 4110 EPS	DT 6100	CC WCWCP 175	CQ 8560	DP 180MXLPS	Xerox Phaser 3600
P 4590 EPS	WC5222	Phaser 6360	Phaser 8500	DP 180MXNPS	WC4150
WC5230	WC5225	Phaser 6280	Phaser 8550	DP 180NPS	Phaser 5500
WC7328	CC WCWCP 35	Phaser 6180	Phaser 8550	Xerox ColorQube 8570N Xerox ColorQube 8570DN Xerox ColorQube 8570DT Xerox ColorQube 8570DX Xerox ColorQube 8870DN	Xerox ColorQube 9301 Xerox ColorQube 9302 Xerox ColorQube 9303
WC7335	CC WCWCP 45	Phaser 4500	Phaser 8560 / MFP	Xerox Workcentre 6400S Xerox Workcentre 6400X Xerox Workcentre 6400XF	Xerox Phaser 6700N Xerox Phaser 6700DN Xerox Phaser 6700DT Xerox Phaser 6700DX
WC7345	CC WCWCP 55	Phaser 6250	Phaser 8860 / MFP	Xerox Versant 2100 Press	Xerox Versant 80 Press
WC7346	CC WCP 90	Phaser 7760	DT 6155	Xerox Phaser 7100N Xerox Phaser 7100DN	Xerox FreeFlow C1000P
CC 32	4112 CP	Phaser 6180 / MFP	Xerox WorkCentre 4265	Xerox Phaser 4510B Xerox Phaser 4510DT Xerox Phaser 4510DX Xerox Phaser 4510N	Xerox FreeFlow C800P
Xerox ColorQube 8580N Xerox ColorQube 8580DN Xerox ColorQube 8880DN	Xerox ColorQube 8700S Xerox ColorQube 8700X Xerox ColorQube 8700XF Xerox ColorQube 8900S Xerox ColorQube 8900X	Xerox Color J75 Press	Xerox Color 800i Press Xerox Color 1000i Press	Xerox Color 8250 Production Printer	

VII.   Caveats for Specific SPARs:

- NA