Readme Document for PrimeLink C9065/9070 Firmware 85.04.51

Release Date: February 21, 2020   **dc20rn03933**

Software Release Details

System Software	Version
System	85.04.51
Controller ROM	1.1.2
IOT ROM	4.60.0
C Finisher	6.3.0
D5-Fin	5.42.0
ADF Software	13.22.0
UI Panel Software	10.16.4
Link to Software	[C9065/C9070](C9065/C9070)

I. Fixes/Features new in this release

Updates to comply with 2020 California Password law (SB-327). This software release supports the California password law SB-327 effective January 1, 2020. The device admin password and SNMP private string will be the device serial number if a memory init is performed. The password is case sensitive.

Security Note: A number of UDP ports (for ex: UDP 49573/50686/54027/59234/62215/ 65280) may be observed to be open on the controller. They are needed by the SMB Client to send data. Those port numbers are randomly generated as a security measure, and may not be the same on different devices.

II. Installation Instructions

This file contains machine firmware and installation instructions. Unzip then download before attempting to install the firmware.