Xerox Wide Format 6705 System Controller SW Release Note V.1.00.29

Created by	Confirmed by C-Cont	Confirmed by P-Cont(PS)	Confirmed by P-Cont	Confirmed by UI	Confirmed by Client	Approved by
'13.12.12 Cont D Gruop CTPF2 Syuichi Hamano	'13.12.13 FXAT DCSW Development Shigeru Oizumi T	'13.12.13 FXAT CSW Development kayuki Kubodera	'13.12.13 Cont Development Gruop CTPF2 Kouichi Suzuki	'13.12.13 Cont Development Gruop CTPF2 Naoki Honma	'13.12.13 Cont Development Gruop CTPF3 Akira Ichikawa	'13.12.16 Cont Development Gruop CTPF2 Tomoyuki Yamada

<Summary>

Bonito Controller SW V1.00.29.00 Release Note

<SW version>

	File Name	Version	Issue Date	Registration name for CVS TAG
Controller SW	cp-cont	1.00.29.00	2013/11/29	Bonito_LONG-REL_1.0. 29.00-20131213
IIT USER	05_User_Iit_s.dat	1.00.03	2012/07/06	
IIT IPS	04_Ips_s.dat	1.00.00	2012/03/30	
IOT	Bonito_Iot_all_Ver1107.mot	1.1.07	2013/11/15	

<Addition/ modification: Print function>

SC No.	Function	Note
	Support for long size print over 15m	P-Cont / UI / C-Cont

<Fixed/ Improved Problems (changes from V1.00.25.00)>

Proweb	AR No.	Problem	Note
	17359	Improved the detecting function when remianing amount of paper is unkown	C-Cont
	17636	Response from SNMP is not returned within specified period of time when acquiring MIB with the large amount of Joblog is stored.	P-Cont
	17655	Displays of Copy-> Paper Cut Mode -> Variable Length are not updated according to the paper information	UI
	17712 17761	System hangs up by entering a user name to "Log In to Local Accounts" after deleting the data collectively.	P-Cont
	17718	Uncompleted JobLog remains in the system after reboot.	P-Cont
	17755	+- buttons are not correctly displayed when the maximum and minimum values are equal.	UI
	17757	Setting of the Energy Saver Timer turns back to the old one, if the Job Recovery is changed after changing the Energy Saver Timer,	P-Cont
	17758	IPv6 manual IP address prefix does not allow the value 0	P-Cont
	17770	Authentication is denied when LDAP is set on UI and IP address is entered only to the secondary server	P-Cont
	17821	Revised the system to allow multiple log-ins of diagnostics when the machine is in Failure/ Error status	C-Cont
	17834	Items below jobId in JobLog are not always listed when "Copy from memory" is performed.	P-Cont

<Limitations>
- Printing over 15m

  - Please note that FX is not providing the printer driver/ printer tools for this function.

  - Maximum value that is allowed to enter is 23,000mm when this function is available.

  - Maximum value for the divide output is 23,000mm when this function is available.

- Network

  - The computer under the Work Group named with over 14 bytes characters cannot be detected on network

- The sysObjectID of the controller is different between FX market products (Japan/IBG) and XC market products.
  Therefore, the following clients that use MIB to detect devices may not work if the setting appropriate for each market is not used.
   - Device detection with NSU3