READ ME—ECAT HCF3 Upgrade Software (Patch ID: 1-LMIND-10.ps)

The Upgrade kit contains the following:

- 45054122—System Software Update CD (patch, printer drivers and user documentation)
- 45054549—Printed User Addendum
- 45054550—Printed Release Notes

Refer to the *User Addendum* for information on how to install the patch and printer drivers provided on the System Software Update CD. Before installing the updated printer drivers from the System Software Update CD, you must manually uninstall existing drivers using the EFI Delete Printer Utility for Windows drivers (see the EXP250 v1.0 user documentation, *Printing From Windows* guide). For Mac driver uninstall instructions, refer to the *User Addendum* provided on the System Software Update CD.

Copyright © 2006 Electronics for Imaging, Inc. Part Number: 45054548

READ ME—ECAT HCF3 Upgrade Software (Patch ID: 1-LMIND-10.ps)

The Upgrade kit contains the following:

- 45054122—System Software Update CD (patch, printer drivers and user documentation)
- 45054549—Printed User Addendum
- 45054550—Printed Release Notes

Refer to the *User Addendum* for information on how to install the patch and printer drivers provided on the System Software Update CD. Before installing the updated printer drivers from the System Software Update CD, you must manually uninstall existing drivers using the EFI Delete Printer Utility for Windows drivers (see the EXP250 v1.0 user documentation, *Printing From Windows* guide). For Mac driver uninstall instructions, refer to the *User Addendum* provided on the System Software Update CD.

Copyright © 2006 Electronics for Imaging, Inc. Part Number: 45054548