RELEASE NOTES

General information	
Issue ID Number	1-EZQ4D
Product Name	Fiery Network Controller for DC3535 v. 1.1
Issue Date	October 14, 2004

Files included in this release	
File name	**File size**
1-EZQ4D.ps	496 Kilobytes
relnotes.pdf	

Issue description

Printed Pantone color seems darker at 81% than 100% with Spot Color Matching = ON.

Steps to reproduce

1. Open file "Spot Color Test" in Quark 6.0 on a Mac OS X.
2. Make two prints. One with Spot Color Matching set to ON. And one with Spot Color Matching set to OFF.
3. Notice on the print with Spot Color Matching set to On that the 81% block appears as dark or Darker than the 100% block.
4. Also compare Pantone 281C blocks 100%, 90% 80% between the Spot color ON and Spot Color OFF. Notice the 90% and 80% of the Spot Color ON are darker than expected.

Resolution type:	Closed - Patch

Resolution

1-EZQ4D.ps

Important notes

TO INSTALL:
Download the patch file with Fiery Downloader or Command Workstation to the Direct Queue. Allow the file to finish processing. A page will be printed confirming that the patch has been downloaded successfully. The system must now be power-cycled for the patch to take effect. Power the system down using the power switch on the front of the copier, wait for it to shut off completely, then turn it back on. Print a configuration page to confirm installation. The Update Info should contain the patch number "1-EZQ4D".

Release Note Template Version 1.0
Created on 10/14/2004 4:12 PM
Last Modified on 10/14/2004 4:12 PM