Release Notes

Product: ColorgrafX X2

Module: Printer Firmware

Version: 1.05.00 **Date:** 5/31/01

The following changes have occurred in the ColorgrafX X2 printer Firmware:

- **SWATH OVERLAP -** "SET -> SWATH OVERLAP" is added. The "Swath overlap" setting is used to change the way that the first four scans of single pass swaths are blended. This swath overlapping is used to minimize the visibility of swath boundaries. In some combinations the original method actually can cause a highly visible line. One example is blue i.e. 100% C and M. This produces a magenta line that can be minimized with magnification and timing adjustments but not eliminated.

- **Quick Check -** "Quick Check" is implemented.

- **Error Code -** Two following errors are added.
  ER:1291 INK I/F PCB DISCONNECTED
  ER:1292 J253 OR J601 DISCONNECTED

- **Online Loading –** Once version 1.05.00 firmware is loaded you can no longer install FW older than version 1.05.00 using the online loader from a host.

- **Color Direct -** The following menu was added in order to enable printing a status sheet from a ColorDirect controller:
  "COLOR DIRECT -> SYSTEM -> STATUS SHEET"

- **SCSI command -** The inquiry command (page 0xc7) which inquires the printing status of X2 is added.

- **A German message is corrected -** The German of the "TEST PRINT -> NOZZLE TEST" menu is corrected as follows.

  Before

GER	MIT INFO	OHNE INFO
ENG	W/O INFO.	WITH INFO.

  After

GER	OHNE INFO	MIT INFO
ENG	W/O INFO.	WITH INFO.

-