


Instructions for Using Xerox HIGH SPEED Paper-Backed Transparencies in DC40 3R5764

* GENERAL USE INSTRUCTIONS *

1. Xerox DC40 High Speed Paper Backed transparencies can be run from the BYPASS TRAY or the HIGH CAPACITY FEEDER (HCF 2500).
2. Load Xerox Paper Backed Transparencies with the paper side down.



Tips for DC40 Mode Selections:

- Heavy Weight Paper Mode
 - Input Size 8.5x11"
 - Paper Supply—Bypass tray (for both bypass tray and HCF 2500)
3. Unused transparencies should be removed from feed tray and stored in original package.

* Notes *

- Color Xpressions High Speed Paper Backed Transparencies offer increased productivity and excellent image quality. However, for premium image quality applications customers may want to use 3R5765 in transparency mode.
- Extended runs of full area coverage transparencies should be interrupted (every 500-800 sheets) with plain paper jobs for increased oil saturation.

FOR INFORMATION / REORDER SUPPLIES CONTACT

1-800-822-2200