

Product Enhancement Document for WorkCentre 3315/3325 Firmware 51.007.13.000

Release Date: December 16, 2019

dc19m3917

Software Release Details


| Component | Versions |
|------------------|------------------------|
| Firmware | 51.007.13.000 |
| MCB | 2.50.07.13 |
| Engine (IOT) | 1.00.34 |
| Network | 4.05.00.18 |
| Link to Firmware | WC3315 (N/A) |
| Link to Firmware | WC3325 |

I. Fixes/Features new in this release

- Wind River VxWorks TCP/IP Stack (IPNet) Vulnerabilities CVE-2019-12257, CVE-2019-12255, CVE-2019-12261, CVE-2019-12263, CVE-2019-12258, CVE-2019-12259, CVE-2019-12262, CVE-2019-12264, CVE-2019-12265

II. Caveats

- 1) NOTE: The Test button for a DFS repository fails even though the actual DFS functionality works.
- 2) Once this digitally signed release is installed, the machine CANNOT be downgraded to a non-digitally signed release. Releases less than v51.003.00.000 are NOT digitally signed



III. Installation Notes

Install instructions are included in the zip file containing firmware. Unzip and download before attempting to install the firmware